



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75625
Promised Date:
24 DEC 24

CUSTOMER WORK ORDER

WO #: 75625

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0102 BH TO CLOSE

Stock #: 11513
Stock Desc: 2025 5W ALLIANCE RV
AVENUE 32RLS
Chassis #: 7M5FA3524SA009926
Serial #: 7M5FA3524SA009926
Mileage: 0
Licence:

Invoice #:
Date In: 04 DEC 24
Promised: 31 DEC 24
Date Sched:
Completed: 30 DEC 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: pdi

CORRECTION: did pdi and everything on sheet,also checked,lp,water,electrical,and appliances.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: winterized unit,did everything on sheet,also had washer hook ups,and ice maker and water dispenser.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C
Z990	WINTERIZE UNIT	DGH	N/C
Z990	WINTERIZE UNIT	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,





Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: TRIM IN CLOSET PULLING AWAY

CAUSE: trim in closet

CORRECTION: restapled trim back in place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	17.00

Subtotal for Job #1: 17.00

Job #2 - Warranty

COMPLAINT: 2 PIECES OF TRIM ABOVE COUCH ARE COMING OFF

CAUSE: 2 pieces of trim coming off

CORRECTION: had to take valance off and restaple trim in place, then stapled other piece in place then reinstalled valance.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00

Subtotal for Job #2: 34.00

Job #3 - Internal

COMPLAINT: 50 AMP CORD MISSING, WAS NOTED ON DELIVERY FORM

CAUSE: THIS WAS DENIED DUE TO DEALER TRASPORT SAYS THERE WAS A CORD

Parts

Part #	Description	Qty	Price	Total
19-6964	A10-5025ED90 50A 90 DEGREE 25' CORD	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total: 0.00
 Labour Total: 51.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 51.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer Signature : _____

Date: 02 Jan 2025

W/O: 75625
Promised Date: 31 DEC 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Customer Work
Order

