

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77106
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11631 - 2025 CATALINA SUMMIT 134RKX 5ZT2CABC8SK011654
VIN: 5ZT2CABC8SK011654 HIN: SER#: 5ZT2CABC8SK011654
Mileage: 0 Work Order Comp: 26 JUL 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 23 JUN 25 Inv #: 420348

WO # Job # Description JOB INFORMATION

77106 4 SHOWER HEAD IS LEAKING
Shower head
The shower head was put on sideways making it leak and when put
on correctly it's not leaking

77106 6 WALLPAPER IS COMING LOOSE
Seam tape is loose
Seam tape is loose and will need to have 2 or 3 staples in it as
well as new seam tape if need replaced

77106 8 LED STRIPE LIGHT ON FRONT NOSE CAP NEEDS REGLUED
Led lights
Led lights were out of track so I pushed them back into track
then added a small amount of silicone sealer to insure they are
waterproof and not going to be ruined by rain

77106 1 ENTRY DOOR NEEDS ADJUSTED
Front door
Adjusted frontdoor by moving the striker plate as well flattened
the hinge out some now door will shut properly

77106 2 REFRIGERATOR IS MAKING A LOUD NOISE WHEN RUNNING
Refrigerator
Refrigerator was making a sound and found out it was a loose
screw in the back of it rubbing

Claim : 77106

 WO # Job # Description JOB INFORMATION

77106 3 KITCHEN AREA NEEDS SILICONED
 Kitchen needed silicone
 Added silicone to the bottom of the base boards to insure that
 the water wouldn't get in and cause water damage

77106 5 SHOWER WALLS NEED SILICONED
 Bathroom needed silicone
 Added silicone sealer to the side that water would go through and
 now is all sealed up

77106 7 BATHROOM DOOR IS NOT SHUTTING
 Bathroom door
 Had to adjust the door latch so the door will shut properly and
 smoother

 Part No Job# Description PARTS Qty Price Total

DFTDF-SA135-W	4	DF-SA135-WT WHITE SHOWER WAND		0.00	11.84	0.00
F100418113	6	TAPE, SEAM 1" GAUZE ASH		6.00	0.21	1.26
SIK432053	8	CLEAR SIKASIL PLUS		1.00	9.17	9.17

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	4	MISC LABOUR CODE (EXTERNAL)		0.05	185.00	9.25
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.05	185.00	9.25
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.05	185.00	9.25
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.15	185.00	27.75
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.07	185.00	12.95
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.03	185.00	5.55
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50

 Excode Job# Description EXTRAS Qty Price Total

FRT	6	FREIGHT		1.00	15.68	15.68
-----	---	---------	--	------	-------	-------

Parts Total: 10.43
 Labour Total: 222.00
 Sublet Total: 0.00
 Extras Total: 15.68

>>>> Claim Total: 248.11

Customer Signature: _____

Date: _____

Claim : 77106

```

*****
Excode      Job#  Description      EXTRAS      Qty      Price      Total
*****

```