



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77266  
Promised Date:  
24 JUL 25



### CUSTOMER WORK ORDER

WO #: 77266 (Appointment Date: 10 JUL 2025 - Time: 09:30am)

Customer: 27089 - DUKE, ALLEN -  
270-570-4799

Tag:

Author: BJW

Location: 0714 BH TO CLOSE

Stock #: 11579

Stock Desc: (11579) 2025 COACHMEN

CATALINA SUMMIT SERIES 261BHS

Chassis #: 5ZT2CARB1SU045761

Serial #: 5ZT2CARB1SU045761

Mileage:

Licence:

Invoice #:

Date In: 10 JUL 25

Promised: 31 JUL 25

Date Sched:

Completed: 12 JUL 25

Warr. Date: 12 APR 25

#### Job #1 - Warranty

COMPLAINT: SCREWS CAME OUT OF TABLE

CAUSE: screws out of dining table

CORRECTION: went inside camper found under the table top that it had 6 screws missing out of it. took one screw out to find correct screw for size. found screws and repalces all screws that had fallen out.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

**Subtotal for Job #1: 37.00**

#### Job #2 - Warranty

COMPLAINT: MINI BLIND BEHIND THE COUCH WILL NOT STAY UP

CAUSE: mini binds behind couch won't stay up

CORRECTION: went to mini blind behind couch and saw that the strings were not wrapped around circle hold for tension string for mini blind. moved the blinds up and wrapped strings around the pice on the bottom of blinds for tension. blinds stay open.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	27.75

**Subtotal for Job #2: 27.75**

#### Job #3 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT WHEN OPENING THE STORAGE COMPARTMENT/DRAWER UNDER THE COUCH, ONE OF THE MAGNETIC KEEPERS COMES OUT WITH THE DRAWER AND IT SHOULD STAY ATTACHED TO THE COUCH SIDE.

CAUSE: magent not staying on storage door under couch.

CORRECTION: took door off storage compartment under couch and three of the four stayed on door while one would stay on couch. took the magent and found that the screw holes had been stripped from the original placement. moved magent over to cover old spots and drilled screws into new placement. tested to make sure the magent would latch on to spot and stay on door when moved. magnet stayed on door and stuck to spot under couch.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00



Customer #: 27089  
DUKE, ALLEN



**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

**Subtotal for Job #3: 37.00**

Parts Total: 0.00  
Labour Total: 101.75  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 101.75**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 12 Jul 2025

W/O: 77266  
Promised Date: 31 JUL 25



Customer #: 27089  
DUKE, ALLEN

