



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77309  
Promised Date: 24 JUL 25

### CUSTOMER WORK ORDER

WO #: 77309 (Appointment Date: 16 JUL 2025 - Time: 01:30pm)

Customer: 55472 - EADS, JASON -

Tag:

Author: GA

Location: 0722 SEE IF BH HAS SPOKE  
WITH FOREST RIVER

Stock #:

Stock Desc: 2022 TT COACHMEN

CATALINA

Chassis #:

Serial #: 5ZT2CATB7NX026014

Mileage:

Licence:

Invoice #:

Date In: 16 JUL 25

Promised: 31 JUL 25

Date Sched:

Completed: 21 JUL 25

Warr. Date:

#### Job #1 - Warranty

COMPLAINT: CAMPER HAS LEAK IN BATHROOM AND RUNS INTO LIVING ROOM WHEN ON CITY WATER.

CAUSE: Vacuum breaker for the black tank flush = stink bugs

CORRECTION: Went into the bedroom and removed the drawers from the wall. Back behind the drawers is the vacuum breaker to the black tank flush. Connected the garden hose to the black tank flush. Had another tech turn on the water while inspecting and checked for a leak. Found the vacuum breaker was leaking. Unscrewed the vacuum breaker and found the stink bugs inside the vacuum breaker. Cleaned out the vacuum breaker and screwed it back on the water lines. Had another tech turn on the water, and no leaks occurred after this fix. Disconnected the hose from the black tank flush. Connected the garden hose to the city water and checked for leaks, no leaks occurred.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	118.40

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

**Subtotal for Job #1: 118.40**

#### Job #2 - Warranty

COMPLAINT: CEILING VENT IN BATHROOM IS LEAKING.REPLACE BOTH VENT COVERS

CAUSE: Replacement of the damaged vent lids

CORRECTION: Went to each vent and opened then unthethe trim ring. When tongue the roof and pulled off the vent lids and matched with new from parts department. Clipped on the new vent lids and assembled the inside ofnthe vent.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	92.50

#### Parts

Part #	Description	Qty	Price	Total
40182	40182 PW VENT LID VENTLINE '08 UP	2.00	14.88	29.76

**Subtotal for Job #2: 122.26**

#### Job #3 - Warranty

COMPLAINT: KITCHEN BLINDS ARE FALLING DOWN.



Customer #: 55472  
EADS, JASON



CAUSE: Dinette blinds

CORRECTION: Checked all the blinds. Found only the dinette blinds that wouldn't stay up. Tightened the tension strings, now the blind stays up.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	37.00

**Subtotal for Job #3: 37.00**

**Job #4 - Warranty**

COMPLAINT: CHECK FRESH WATER TANK

CAUSE: Fresh tank

CORRECTION: Checked the fresh tank found it had water. Opened the drain to the fresh tank.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	55.50

**Subtotal for Job #4: 55.50**

**Job #5 - Warranty**

COMPLAINT: INSTALL ROOF VENT COVERS

CAUSE: New vent lid covers

CORRECTION: Received vent lid covers from the parts department. Opened the vent lids. Went on the roof then mounted the brackets to hold the covers. Bolted down the vent covers and went inside the camper to check for clearance.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	92.50

**Subtotal for Job #5: 92.50**

Parts Total:	29.76
Labour Total:	395.90
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>425.66</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 21 Jul 2025

W/O: 77309  
Promised Date: 31 JUL 25



Customer #: 55472  
EADS, JASON

