



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77361  
Promised Date:  
24 11 25

### CUSTOMER WORK ORDER

WO #: 77361

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 0815 BH TO CLOSE

Stock #: 11642  
Stock Desc: 2026 TT KEYSTONE  
SPRINGDALE 224MLC  
Chassis #: 4YDTSKG2XT7100162  
Serial #: 4YDTSKG2XT7100162  
Mileage: 0  
Licence:

Invoice #:  
Date In: 23 JUL 25  
Promised: 31 JUL 25  
Date Sched:  
Completed: 18 AUG 25  
Warr. Date:



#### Job #PDINTT - Internal

COMPLAINT: Transferred to BAS\*77462 on 04 AUG 25  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

CAUSE: Pdi new

CORRECTION: Started on new pdi  
Checked all exterior lights,tires, checked roof and seals on windows, checked all interior lights and outlets, checked all cabinets and also doors all shut, ran all antifreeze out of lines also checked for leaks, checked all flooring for cracks and no evidence of any showing, checked all beds,filled lp also did the drop test while checking the furnance and water heater and working correctly, checked tv connection and is working correctly,Furance is working properly as well as ac, smoke detector is working/ carbon monoxide detector is working, refrigerator and microwave are working properly, drained all black and grey tanks

#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

#### Job #1 - Warranty

COMPLAINT: KITCHEN BLIND BROKEN WHEN UNIT WAS DELIVERED

CAUSE: Missing blind.

CORRECTION: Unboxed blind. Removed packaging. Drilled two holes in back of blind. Shoot screw through each hole. Blind goes up and down and shuts. Blind is in place.

#### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	0.00
Z990	MISCELLANEOUS REPAIR	CCV	36.00

#### Parts

Part #	Description	Qty	Price	Total
625932	26x32 MINI BLIND ALUM MATTE BLACK -	1.00	6.09	6.09

Customer #: 1000  
BASDEN'S AMERICAN RV,



W/O: 77361  
Promised Date: 31 JUL 25

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-BLIND	1.00	15.88	15.88
<b>Subtotal for Job #1:</b>				<b>57.97</b>

**Job #2 - Warranty**

COMPLAINT: REAR AWNING HEAD COVER IS BROKEN AND FALLING APART

CAUSE: Missing awing cap

CORRECTION: Plugged in camper. Ran awing out a foot to expose arm topper. Place cap in place. Clicked front and back pieces together. Cap sits firm in place

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	36.00

**Parts**

Part #	Description	Qty	Price	Total
623560	Awning - Service Kit - Cover - Head	1.00	23.04	23.04

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-AWN CAP	1.00	16.74	16.74
<b>Subtotal for Job #2:</b>				<b>75.78</b>

Parts Total:	29.13
Labour Total:	72.00
Sublet Total:	0.00
Extras Total:	32.62
<b>WORK ORDER TOTAL:</b>	<b>133.75</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 18 Aug 2025

Customer #: 1000  
BASDENS AMERICAN RV,

