



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77372
Promised Date:
24 JUL 25

CUSTOMER WORK ORDER

WO #: 77372

Customer: 56033 - HUFF, MARC -

Tag: 6

Author: GA

Location: 1030 CHECK PREAUTH

Stock #:

Stock Desc: 2021 FOREST RIVER

SALEM SFX

Chassis #:

Serial #: 5ZT2SMFC0MG071528

Mileage:

Licence:

Invoice #:

Date In: 24 JUL 25

Promised: 31 JUL 25

Date Sched:

Completed: 29 OCT 25

Warr. Date:

Job #1 - External

Transferred to BAS*77892 on 24 SEP 25

Estimate amount was 0.00

FIX WEATHER STRIPPING INSERT ON FRONT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - External

ESTIMATE TO FIX WINDOW ON DOOR SIDE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Subtotal for Job #2: 0.00

Job #22V729 - Warranty

COMPLAINT: RECALL ON HOLDING TANK

CAUSE: Fresh tank strap recall

CORRECTION: Im not sure if there is/was a underbelly panel here at the fresh tank but tank is full and sagging a good 6in beyond the frame. Drained the tank, had to use a board a a jack to rwise the tank for the majorityof the water to drain. Removed the screws that held up the next panel towards the the front to expose the cross frame. Had to predrill holes in the straps backend where the crossmember instructed to mount strap because the axle was in the way and the corner brackets on fresh tank was mounted lower then the frame which made it harder to drill and installed self tap screws into frame. Had to use jack with board to hold the strap and push fresh tank upwards so support straps would reach frame on both end. Repeated the process on other 2 straps. Reinstalled underbelly.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	370.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00

Customer #: 56033
HUFF, MARC



Subtotal for Job #22V729: 370.00

Job #ROOFT - External

Transferred to BAS*78093 on 21 OCT 25

Estimate amount was 0.00

INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF SEALANT INCLUDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #3 - External

Transferred to BAS*78093 on 21 OCT 25

Estimate amount was 0.00

FINISH DICOR FROM ROOFT AND SIDE WALLS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #3: 0.00

Parts Total: 0.00
Labour Total: 370.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 370.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Oct 2025

W/O: 77372
Promised Date: 31 JUL 25



Customer #: 56033
HUFF, MARC

