



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77389
Promised Date:
20 AUG 25

CUSTOMER WORK ORDER

WO #: 77389 (Appointment Date: 26 JUL 2025 - Time: 10:00am)

Customer: 43532 - MILLER, MISTY L. -
812-899-0578

Tag:

Author: BH

Location: 0826 CHECK STATUS WITH
SAR

Stock #: 11601

Stock Desc: 2025 TT COACHMEN

FREEDOM EXPRESS 245RKS

Chassis #: 5ZT2FEPB7SW031112

Serial #: 5ZT2FEPB7SW031112

Mileage: 0

Licence:

Invoice #:

Date In: 26 JUL 25

Promised: 30 AUG 25

Date Sched:

Completed: 26 AUG 25

Warr. Date: 31 MAY 25

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE SHOWER IS
LEAKING ON THE FRONT SIDE BY THE RAIL.
CUSTOMER ADVISES THAT THE WOOD UNDER THE
SHOWER HAS WATER MARKS AND THE PANELING
UNDER THE SHOWER HAS WATER MARKS AS WELL
AND THE FLOORING IN FRONT OF THE SHOWER
IS YELLOWING. CUSTOMER REQUEST THAT ALL
OF THE DAMAGED WOOD BE REPLACED

CAUSE: Shower door was leaking
Paneling

CORRECTION: I found that the insert trim did not fit flush at the top. This would not allow the door sealed to
make full contact. I also found that the inside of the lower track had not been sealed behind the insert trim.
This was letting water leak out the corner of the shower door opening. I sealed up inside the lower corner
behind the insert trim. I trimmed the insert so that it would fit flush against the wall. Now the door closes all
the way. I tested the corner to see if it would leak. The water now drains out the way it should.
Got with Ben and discussed about the paneling below the shower pan. Took pictures of the paneling.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	223.85
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	53.65

Parts

Part #	Description	Qty	Price	Total
F100615388	PANELING 4x8 CANYON PEBBLE	1.00	48.01	48.01

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT & CRATE - PANELING	1.00	142.35	142.35

Subtotal for Job #1: 560.36

Job #2 - Warranty

COMPLAINT: THE VALANCE ABOVE THE DINNETTE HAS FELL DOWN AND NEEDS TO BE
INSTALLED BACK

CAUSE: Screws pulled out of wall

CORRECTION: I reinstalled the upper valance that holds the mini blind. I used 4 new screws that are a little
larger than the original.



Customer #: 43532
MILLER, MISTY L.



Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	37.00
Subtotal for Job #2:			37.00

Job #3 - Warranty

COMPLAINT: LIGHT ABOVE THE KITCHEN SKIN IS BLINKING

CAUSE: Customer states light over sink flickers.

CORRECTION: I left the light on while I was working on the shower. The light remained on while I was working on the mini blind valence. I did not see the light flicker at all. I unplugged the unit to let the battery voltage drop a bit, and then I plugged it back in. This let the converter work harder and I was able to see the LED light over the sink flicker for a short time until the battery voltage came back up. I found that the fridge would also make the lights flicker when it was running. I tried adding 2 filter loops and that did not fix the problem. I tried running a new ground wire for the lights and that did not fix the problem. I unhooked the ground wire for the fridge and used jumper cables to ground it to the frame. This stopped the lights from flickering. So I ran a new ground wire to the frame and hooked up the fridge ground wire to it. I put everything back together and the lights are working as they should.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	329.30
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	40.70
Subtotal for Job #3:			370.00

Job #4 - Internal

COMPLAINT: CHECK THE HITCH CUSTOMER STATES THAT IT HAS MOVED

CAUSE: Found that the brackets did move a little bit.

CORRECTION: I really adjusted the hitch brackets. I tighten them down so they will not move again.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Subtotal for Job #4:			0.00

Parts Total:	48.01
Labour Total:	777.00
Sublet Total:	0.00
Extras Total:	142.35
WORK ORDER TOTAL:	967.36

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Aug 2025

