



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77422

CUSTOMER WORK ORDER

WO #: 77422

Customer: 26204 - COX, CHRISTOPHER
R - 812-303-2185

Tag:
Author: BH

Location: 0811 CHECK DELIVERY

Stock #: 11508

Stock Desc: 2025 TT COACHMEN
REMOTE 19R

Chassis #: 5ZT2RMHC1SL018317

Serial #: 5ZT2RMHC1SL018317

Mileage:

Licence:

Invoice #:

Date In: 30 JUL 25

Promised:

Date Sched:

Completed: 31 JUL 25

Warr. Date: 31 JUL 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly air pressure correct in all 3 tires. Installed new battery. And had to shot the battery box to the frame. Exterior inspection door needs adjusted hitting on the striker. Adjusted the striker door shuts properly now and exterior inspection looks good. Roof inspection found some voids in the sealer that I filled with dicor self-leveling. Roof good now. Interior inspection hooked up to city water and flushed out all the lines including outdoor shower. Stove and microwave works properly. Had to remove shipment packing from microwave. refrigerator works properly. Had to remove the packing tape from inside the refrigerator. Ac and furnace works properly water heater works properly the tv doesn't get signal because there isn't a TV antenna on roof. Had to replace city fill port because water was coming out it when running the water pump. I replaced it with a new one and it works properly now.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Internal

WHEN DRP WROTE NO HITCH WORK 7-30



Customer #: 26204
COX, CHRISTOPHER R



Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CITY WATER LEAKING WHEN ON PUMP

CAUSE: Water was coming out the city fill when water pump was running

CORRECTION: Unscrewed the city fill port and disconnected it from the bad city fill port and hooked it to the new city fill port and ran the water pump and the pump works properly and water doesn't come out the city fill port.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50

Parts

Part #	Description	Qty	Price	Total
94215	CITY WATER FILL W/BRASS CHECK VALVE, BLACK	1.00	15.01	15.01

Subtotal for Job #2: 107.51

Parts Total: 15.01
 Labour Total: 92.50
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 107.51

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Aug 2025

W/O: 77422



Customer #: 26204
COX, CHRISTOPHER R

