



Warranty Authorization Form

Date: 8/20/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 102495 Unit: 7M5FP3624SB205842
Series: Paradigm Model: 2025PAR310RL
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 14075 PANEL - INTERIOR WALL - REPAIR
(Photos required)

Fault Code: LOOSE

Serial #:

Model #:

Notes:

Problem: Back of living room TV's screws came through.

Time Requested: .2

Cause: Blocking for tv mount not secure

Time Allowed: .2

Remedy: Took out screw push on the blocking reshot. The screw to pull it up tight looks better now.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 14085 TRIM - INTERIOR - REPAIR

Fault Code: LOOSE

Serial #:

Model #:

Notes:

Problem: Strip on the ceiling and the bedroom has come loose

Time Requested: .1

Cause: Ceiling strip coming down

Time Allowed: .1

Remedy: Seasoning strip coming down in master bedroom.I glued it back up.It looks good

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved