



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77524
Promised Date:
20 AUG 25

CUSTOMER WORK ORDER

WO #: 77524 (Appointment Date: 11 AUG 2025 - Time: 11:00am)

Customer: 45604 - PARKER, DAVID -
812-228-7268

Tag:

Author: GA

Location: 0915 BH TO CLOSE

Stock #: 11487

Stock Desc: (11487) 2025 KEYSTONE
COUGAR HALF-TON 29RLI

Chassis #: 4YDFCGN2XS2502426

Serial #: 4YDFCGN2XS2502426

Mileage:

Licence:

Invoice #:

Date In: 11 AUG 25

Promised: 30 AUG 25

Date Sched:

Completed: 15 SEP 25

Warr. Date: 18 NOV 24

Job #1 - Warranty

COMPLAINT: THE ACCUSLIDE IN THE BEDROOM IS MAKING A VERY LOUD (GEAR GRINDING) SOUND AND THE ROOM IS OUT OF TIME.

CAUSE: Bent gearbox

CORRECTION: Received the new motor and gearbox. Pulled the camper up to the service bay then opened the bedroom slideroom with help from another tech. Unbolted the cables from the slideroom. Pulled off the bulb seal. Unscrewed the exterior screws on the front side of the slideroom. Disconnected the power from the slideroom motor. Unbolted the slideroom motor from the slide housing. Pulled out the bad slide motor. Placed in the new slide motor and bolted into the slide housing. Pushed the slide housing back into the exterior wall. Wired the power to the slide motor. Screwed the slide housing to the exterior wall. Bolted the cables back on the slideroom. Got the tension tool then tightened the cables then ran the slideroom out and in 3 times as it synchronized. Tightened the cables again. Screwed the facia boards to the slideroom and siliconed the final trim. Closed up the slideroom.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	196.20
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	79.20
Z990	MISCELLANEOUS REPAIR	SAR	127.80
Z990	MISCELLANEOUS REPAIR	SAR	136.80

Parts

Part #	Description	Qty	Price	Total
720136	Actuator - Motor Kit - RH - 20201190	1.00	233.09	233.09

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SLIDE MOTOR	1.00	14.98	14.98

Subtotal for Job #1: 788.07

Job #ROOFT - External

Transferred to BAS*77738 on 04 SEP 25

Estimate amount was 0.00

INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF SEALANT INCLUDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C



Customer #: 45604
PARKER, DAVID

W/O: 77524
Promised Date: 30 AUG 25



Customer #: 45604
PARKER, DAVID



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #3 - External

Transferred to BAS*77738 on 04 SEP 25

Estimate amount was 0.00

FAN IN BATHROOM ROOF VENT DOESN'T COME ON

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #3: 0.00

Job #4 - External

Transferred to BAS*77738 on 04 SEP 25

Estimate amount was 0.00

LIGHTS IN LIVING ROOM SLIDE DOES NOT COME ON

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #4: 0.00

Parts Total: 233.09
Labour Total: 540.00
Sublet Total: 0.00
Extras Total: 14.98
WORK ORDER TOTAL: 788.07

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Sep 2025

