



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77592
Promised Date:
20 AUG 25



Customer #: 55700
MCCLURE, RYAN



CUSTOMER WORK ORDER

WO #: 77592 (Appointment Date: 19 AUG 2025 - Time: 10:30am)

Customer: 55700 - MCCLURE, RYAN -
812-470-8484

Tag:

Author: BJW

Location: 0826 BH TO CLOSE

Stock #: 11628

Stock Desc: (11628) 2026 FOREST
RIVER CHEROKEE WOLF PUP 17JW

Chassis #: 5ZT2CKFC3TY038906

Serial #: 5ZT2CKFC3TY038906

Mileage:

Licence:

Invoice #:

Date In: 19 AUG 25

Promised: 30 AUG 25

Date Sched:

Completed: 26 AUG 25

Warr. Date: 22 JUL 25

Job #1 - Warranty

COMPLAINT: CUSTOMER LIFTED MAIN DOOR HANDLE ON CAMPER AND IT FELL APART.

CAUSE: Broken Grabbar

CORRECTION: Took pics and measured, 22in from top to bottom including the mounts. Received replacement grab bar and installed it.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	7.40
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	7.40
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	22.20

Parts

Part #	Description	Qty	Price	Total
42197	42197 SHORT BLK GRAB HANDLE - CAMCO	1.00	31.99	31.99

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 68.99

Job #2 - External

COMPLAINT: CUSTOMER THINKS THAT UNIT IS PREPPED FOR LIPPERT COLLAPSABLE LADDER. HE WOULD LIKE FOR US TO CHECK AND CONFIRM IF IT IS OR NOT. UNIT DOES NOT HAVE LADDER HANGER INSTALLED.

CAUSE: .

CORRECTION: Looked unit over and spoke with Ben in regards to collapsible ladder and no this unit is not setup for it.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #2: 0.00



W/O: 77592
Promised Date: 30 AUG 25

Parts Total:	31.99
Labour Total:	37.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	68.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Aug 2025

Customer Work
Order



Customer #: 55700
McCURE, RYAN

