



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77663



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 77663

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0902 SEE IF CHRIS HAS
PHOTOS YET

Stock #: 11658
Stock Desc: 2026 TT COACHMEN
CATALINA SUMMIT 261BHS
Chassis #: 5ZT2CARB2TU047097
Serial #: 5ZT2CARB2TU047097
Mileage: 0
Licence:

Invoice #:
Date In: 27 AUG 25
Promised:
Date Sched:
Completed: 30 AUG 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Torqued tires to 110 ft lbs. Brought all tires to 65psi. Took model and serial numbers for all appliances. Fridge, range top, range fan, furnace, microwave, and water heater work. All plumbing works on city water. All interior lights work. Ran lp drop test unit passed. All appliances working. Interior looks good. Water pump works. Inlets all work. Co2 and smoke detector work. Ac unit works. Lp tanks filled. Stereo system works. All windows open and close properly. All clearance lights work. Turn lights work. Breaks and ebreaks work. Inspected roof. Roof is in good condition with no voids. Jacks and leveling system works. Plumbing works with water pump. All antifreeze cleared from camper. Used test tv to make sure connection worked and it does picture comes through.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: LIVING ROOM CEILING LIGHT STOPPED
WORKING

CAUSE: Light flickering then not working.

CORRECTION: During pdi i noticed living room light by fridge was flickering then stopped working. Removed screws from light then cut wires to light. Replaced with new light by attaching wires together. Made sure light turns on and it does. Put screws back into light and put cover on.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00



Parts

Part #	Description	Qty	Price	Total
479579	LED - Mushroom Light - Ultra Bright	1.00	3.02	3.02

Subtotal for Job #1: 40.02

Job #2 - Warranty

COMPLAINT: GUTTER ON THE DOOR SIDE IS FALLING OFF

CAUSE: Gutter spout falling off

CORRECTION: During pdi noticed the gutter spout was falling off of camper. Pulled off from spout. Had to removed sealent around gutter and removed to screws from side to be able to put gutter spout back in place. Put screws back in to secure spout and put black non sag where it was removed to access screw.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Parts

Part #	Description	Qty	Price	Total
3388	551LSB-1 BLACK NON SAG DICOR	1.00	8.72	8.72

Subtotal for Job #2: 64.22

Job #3 - Warranty

COMPLAINT: WINDOW STRING GOT CAUGHT IN THE WINDOW TRIM RING

CAUSE: String caught in window ring.

CORRECTION: During pdi i noitced the string for the blings was caught in the window frame ring. Removed the two screws on the side of window. Pulled string out. Placed screws back in. Strings are now free.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	9.25
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50

Subtotal for Job #3: 27.75

Job #4 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Entry door not shutting

CORRECTION: Moved striker plate forward. Still not shutting tight. Saw middle hinge was not as far in as rest. Took a light mallet to strike hinge. Adjsuted door slightly but was still a little off. Door was also bowed so bent door slightly to try to straighten out. Door shuts better

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Subtotal for Job #4: 55.50

Parts Total: 11.74
Labour Total: 175.75
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 187.49



Customer #: 1000
BASDEN'S AMERICAN RV,



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Sep 2025

W/O: 77663



Customer #: 1000
BASDEN'S AMERICAN RV,



Customer Work
Order

