



Warranty Authorization Form

Date: 9/26/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 106176 Unit: 7M5FA332XTA011863
Series: Avenue Model: 2026AVE29RL
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 20038 SPRAY PORT - REPLACE (part return in US) *Fault Code:* VENDOR

Serial #:

Model #:

Notes: Changed flat rate code

Problem: THE QUICK CONNECT LEAKS WHEN IT IS CONNECTED

Time Requested: .2

Cause: Leaking out of backside of quick connect

Time Allowed: .2

Remedy: Replaced faucet.

Sublet Repairs: 0.00

Part Return Req: Yes

Status: Approved