



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77686  
20 SEP 25  
Promised Date:

### CUSTOMER WORK ORDER

WO #: 77686

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: GA  
Location: 1001 CHECK PREAUTH

Stock #: 11660  
Stock Desc: 2026 5W ALLIANCE RV  
AVENUE 23ML  
Chassis #: 7M5FA2828TA011847  
Serial #: 7M5FA2828TA011847  
Mileage: 0  
Licence:

Invoice #:  
Date In: 29 AUG 25  
Promised: 30 SEP 25  
Date Sched:  
Completed: 30 SEP 25  
Warr. Date:

#### Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: Pdi.

CORRECTION: Pulled the speaker and inspected the wires. Tested wires leading to speaker. Removed the radio and inspected the wires. One side is on channel A and the other is on B. Swapped wires to side A and the speaker is now working. Installed radio and speaker.

#### Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

**Subtotal for Job #PDINFW: 0.00**

#### Job #1 - Internal

COMPLAINT: ADJUST ENTRY DOOR. HARD TO OPEN

CAUSE: Door is hitting the latch plate. There is also a screw missing on the door plate.

CORRECTION: Moved door latch over with a hammer. Sending parts to try and get a screw that fits the door.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

**Subtotal for Job #1: 0.00**

#### Job #2 - Warranty

COMPLAINT: GREY TANK WON'T READ

CAUSE: Filled the grey tank up and it wouldn't read. Draned the tank. Cut the underbelly and located the grey tank. Checked wires and connections. Went inside and removed the controll panel. Inspected all wires and connections. I found a grey wire that didnt have anything on it.



Customer #: 1000  
BASDEN'S AMERICAN RV,



CORRECTION: Hooked up city water and started filling the grey tank. Hooked up the grey wire coming through the eall and secured it to the grey wire that comes off the board. The grey tank is reading. Installed controll panel. Taped up underbelly.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	277.50
<b>Subtotal for Job #2:</b>			<b>277.50</b>

**Job #3 - Warranty**

COMPLAINT: SPEAKER ON INSIDE IS INOP

CAUSE: Speaker inop.

CORRECTION: Pulled the speaker and inspected the wires. Tested wires leading to speaker. Removed the radio and inspected the wires. One side is on channel A and the other is on B. Swapped wires to side A and the speaker is now working. Installed radio and speaker.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00
<b>Subtotal for Job #3:</b>			<b>37.00</b>

**Job #4 - Warranty**

COMPLAINT: THE BLACK TANK FLUSH IS LEAKING

CAUSE: the vaccum breaker for the tank flush is leaking.

CORRECTION: The fittings are tight. removed and replaced cone washers. turned on water hose and tested. no leaks present after replacing the cone washers

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	138.75
<b>Subtotal for Job #4:</b>			<b>138.75</b>

Parts Total:	0.00
Labour Total:	453.25
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>453.25</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 02 Oct 2025

