



Pre-Authorization number	PREAUTH125 74 (PA03906979	Reference no.77712	Status	Approved
--------------------------	---------------------------------	--------------------	--------	----------

Root		Approved Actual				Base		
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
6101206A	Fresh Water Tank Fill - Repair	0	2	0		1	0.2	Complaint: WHEN TURNING THE VALVE TO CITY FRESH TANK AND FILL THE WATER PUMP TURNS ON Cause: please let me know what is wrong Correction: dont know fix please call KRV- Spoke with Ben No Defect Presented
6200206B	LP Bottle - Replace	0	0.4	0.4		1	0.2	Complaint: BOTH LP TANKS WILL NOT FILL Cause: valves will not fill need to replace Correction: replaced the tanks KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item.
Pre-Authorization number: PREAUTH12574				0.4				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.