

BASDEN RV CENTER, INC dba AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 77754
 MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
 Customer: 1000 - BASDEN'S AMERICAN RV
 Address: 600 E. BASELINE RD. EVANSVILLE, IN
 USA
 47725
 Phone:
 Stock Number: 11663 - 2026 SPRINGDALE 269DBC 4YDTSGM25T7100857
 VIN: 4YDTSGM25T7100857 HIN: SER#: 4YDTAGM25T7100857
 Mileage: 0 Work Order Comp: 29 SEP 25
 Auth. No: Dealer #: 1194
 Warr. Date: Work Order Date: 05 SEP 25 Inv #: 422610

```

*****
WO #      Job #   Description          JOB INFORMATION
*****
77754     4       3 WINDOWS ARE MISSING SEALER
          Gaps in window
          During a pdi noticed gaps in window were it was just metal and no
          foam. Taped off window and put clear silicone im gap to fill. Ran
          finger to round off and clean excess silicone off.

77754     1       ENTRY DOOR NEEDS ADJUSTED
          Entry door needs adjusted
          During pdi noticed entry door was not shutting properly and
          wouldnt latch. Adjust striker plate by moving bottom end forward
          and tightened back. Checked and door latches better

77754     2       THE AWNING ARM KEEPS GETTING STUCK
          Awning arm hanging up
          During pdi i noticed awining arm was hanging up. Saw a gap from
          arm to mount. Took screws out and adjusted over. Arm opens and
          shuts well.

77754     3       SHOWER CONNECTION IS LEAKING
          Leaking from shower connection
          During pdi noticed water was leaking from threads of shower. Took
          shower head connection off and and cleaned out where threads
          were. Onced clean out reconnected to shower. Checked for leaks
          amd non were found.
  
```

```

*****
Part No   Job#   Description          PARTS          Qty   Price   Total
*****
SIK432053  4     CLEAR SIKASIL PLUS          1.00   10.36   10.36
  
```

Claim : 77754

```

*****
Part No      Job#  Description      PARTS          Qty    Price    Total
*****

```

```

*****
Lab Code  Job#  Description      LABOUR          Hrs    Rate    Total
*****
Z990      4    MISCELLANEOUS REPAIR          0.20   180.00   36.00
Z990      1    MISCELLANEOUS REPAIR          0.20   180.00   36.00
Z990      2    MISCELLANEOUS REPAIR          0.20   180.00   36.00
Z990      2    MISCELLANEOUS REPAIR          0.00   180.00    0.00
Z990      3    MISCELLANEOUS REPAIR          0.50   180.00   90.00

```

```

Parts Total:      10.36
Labour Total:     198.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 208.36

Customer Signature: _____

Date: _____