



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77754



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 77754

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1001 CHECK PREAUTH

Stock #: 11663
Stock Desc: 2026 TT KEYSTONE
SPRINGDALE 269DBC
Chassis #: 4YDTSGM25T7100857
Serial #: 4YDTSGM25T7100857
Mileage: 0
Licence:

Invoice #:
Date In: 05 SEP 25
Promised:
Date Sched:
Completed: 29 SEP 25
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Entry door needs adjusted

CORRECTION: During pdi noticed entry door was not shutting properly and wouldnt latch. Adjust striker plate by moving bottom end forward and tightened back. Checked and door latches better

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	36.00

Subtotal for Job #1: 36.00

Job #2 - Warranty

COMPLAINT: THE AWNING ARM KEEPS GETTING STUCK

CAUSE: Awning arm hanging up

CORRECTION: During pdi i noticed awining arm was hanging up. Saw a gap from arm to mount. Took screws out and adjusted over. Arm opens and shuts well.

Labor



Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	36.00
Z990	MISCELLANEOUS REPAIR	CCV	0.00

Subtotal for Job #2: 36.00

Job #3 - Warranty

COMPLAINT: SHOWER CONNECTION IS LEAKING

CAUSE: Leaking from shower connection

CORRECTION: During pdi noticed water was leaking from threads of shower. Took shower head connection off and and cleaned out where threads were. Onced clean out reconnected to shower. Checked for leaks amd non were found.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	90.00

Subtotal for Job #3: 90.00

Job #4 - Warranty

COMPLAINT: 3 WINDOWS ARE MISSING SEALER

CAUSE: Gaps in window

CORRECTION: During a pdi noticed gaps in window were it was just metal and no foam. Taped off window and put clear silicone im gap to fill. Ran finger to round off and clean excess silicone off.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	36.00

Parts				
Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	10.36	10.36

Subtotal for Job #4: 46.36

Parts Total: 10.36
Labour Total: 198.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 208.36

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 29 Sep 2025

Customer Signature : _____

W/O: 77754



Customer #: 1000
BASDENS AMERICAN RV,

