

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 77816  
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC  
Customer: 32316 - KEVIN KAISER  
Address: 501 SECTION ST NEWBURGH, IN

47630

Phone: 812-453-1043

Stock Number: 11647 - 2026 DELTA 262RB 7M5TD292XTC307174

VIN: 7M5TD292XTC307174 HIN: SER#: 7M5TD292XTC307174

Mileage: 0 Work Order Comp: 30 OCT 25

Auth. No: Dealer #:

Warr. Date: 15 AUG 25 Work Order Date: 15 SEP 25 Inv #: 423821

```
*****
WO #      Job #   Description      JOB INFORMATION
*****
77816     3      THERE IS BLIND MISSING NEAR THE SINK AND STOVE      (((WINDOW IS
36X15)))
Blind
Parts ordered installed new blind had to get 1 brackets and
mount under the cabinet .

77816     5      LOOK AT THE ROOF THE SEALANT IS NOT SKINED OVER AND LEAVES AND
DESBRE STICKS TO IT
Roof
Took pics

77816     6      BLIND ON THE END OF THE SLIDE WILL NOT ROLL UP ON THE REAR MIGHT
BE THE ONLY ONE DOWN
Blind
Removed blind and adjusted screws on the side. Tested. Works good
installed new blind

77816     8      THE SEAL IN THE OUTSIDE COMPARTMENT ON THE SLIDE ROOM IS COMING
OFF
found the the compartment door was leaking
replaced the seal and it stopped

77816     1      small wall in the slide room has come apart and cable for the usb
charger have came apart and needs to be put back together
Bench seat
Removed panel. Removed screws holding front trim. Put screws in
```

Claim : 77816

\*\*\*\*\*  
 WO # Job # Description JOB INFORMATION  
 \*\*\*\*\*

new spot. Removed screws on upper trim. Put back in nea spot.  
 Staped back panel and putty holes.

77816 4 THE USB IS NOT WORKING IN THE SLIDE ROOM NEAR THE RECLINER  
 Port  
 Wired up USB port

77816 7 CHECK THE SLIDE ROOM IT IS NOT MAKING A CLUTCHING SOUND BUT  
 CUSTOMER SAYS IT IS CLOSED MIGHT NEEDS TO BE ADJUSTED  
 Slideroom  
 Took pics of slideroom in to far. Opened up and adjusted to shut  
 right. Moved bell in.

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
24279	3	Shade - Roller - Night - 38 x 20		1.00	30.20	30.20
24672	3	WINDOW VALANCE - ALLIANCE		1.00	48.75	48.75
12165	5	XTRM WHITE SELF LEVELING LAP SEAL		16.00	6.68	106.88
24277	6	Shade - Roller - Night - 26 x 32		1.00	29.39	29.39
299894	8	.5" RIBBED DOOR SEAL		10.00	0.57	5.70

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		2.00	185.00	370.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		1.25	185.00	231.25
Z990	5	MISC LABOUR CODE (EXTERNAL)		1.25	185.00	231.25
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50

\*\*\*\*\*

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	3	UPS-SHADE & VALANCE		1.00	12.53	12.53
FRT	6	UPS-SHADE		1.00	12.53	12.53
SS	1	SHOP SUPPLIES		1.00	0.00	0.00

Claim : 77816

\*\*\*\*\*  
Excode Job# Description EXTRAS Qty Price Total  
\*\*\*\*\*

Parts Total: 220.92  
Labour Total: 1,332.00  
Sublet Total: 0.00  
Extras Total: 25.06

>>>> Claim Total: 1,577.98

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_