



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77829
Promised Date:
17 SEP 25

CUSTOMER WORK ORDER

WO #: 77829

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1001 CHECK PREAUTH

Stock #: 11655
Stock Desc: 2026 TT COACHMEN
CATALINA SUMMIT 261BHS
Chassis #: 5ZT2CARB3TU047027
Serial #: 5ZT2CARB3TU047027
Mileage: 0
Licence:

Invoice #:
Date In: 16 SEP 25
Promised: 17 SEP 25
Date Sched:
Completed: 26 SEP 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Brought unit in. Torqued lug nuts to 110ft lbs. Brought all tires including spare to 65psi. Checked roof to be clear of voids or other issues. Attached battery box. Insereted battery. Checked clearance lights and break lights as well as front cap leds to be all working correctly. Removed lp tanks from unit and put on lp cart. Ran tanks outside and filled and put back onto unit. Jacked both axels and checked breaks and ebreaks to be working all around. Ran awning out fabric was in good condition and awning lights work. Awning light remote works. Plumbing works on city water. Toleit model taken. All outlets work. Stero works. Microwave works. Range top works. Range fan works. All windows and screens work properly. Water heater works. Tested tv at living room and bedroom connection and picture came through at both. Outside fridge and griddle work. Furnance works. Smoke detector and co2 sensor work. Water pump works. Chevkec 12v system tobe working. Unit passed lp drop test. Toungue jack and leveling system with stablizer jacks work. Black tank flush missing vent screen so ine was added to it. Stablizer jacks retract well. Slideroom goes in and out well. Tank valves work well. Interior looks good. Entry door locks well and step adjust,ent works. Ac unit works.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
10-1211	20183 3-PK 1" HOSE FILTERS	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: GREY TANK NOT READING ON MONITOR

CAUSE: Grey tank not reading

CORRECTION: During pdi i noticed grey tank was not reading. Checked to make sure all terminals were were getting power. Checked ground to make sure it was getting a good read. Found tank wire and



Customer #: 1000
BASDEN'S AMERICAN RV,





followed all they was to make sure there was not a cut anywhere.checked voltage at each terminal when able to get tester to terminal, normal voltage. Took cover off of control board to check voltage at wire on board. Normal voltage.Tested resistance at tank wire brain. Could not reach actual senors because they are pushed against frame. Tried to get to ground but it is in difficult to reach area. Brain had rersistence on all three wires. Believe ground had been inserted into tank wrong to were it cannot read. Ran new ground into tank. Drilled hole and then added terminal for new ground. Ran tank unitl full to check all sensors tombe working. Crimped wires back together

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	185.00

Parts

Part #	Description	Qty	Price	Total
10-1165	SCREW IN SENSOR PROBE	1.00	1.21	1.21
Subtotal for Job #1:				278.71

Parts Total:	1.21
Labour Total:	277.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	278.71

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Sep 2025

