




600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77832



CUSTOMER WORK ORDER

WO #: 77832

Customer: 1000 - BASDEN'S AMERICAN RV -

Tag:
Author: BH

Location: 1005 CHECK PREAUTH see if ashlee has got forest river to pay for the door

Stock #: 11657

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE GREY WOLF 29NM

Chassis #: 4X4TCKE29TK097079

Serial #: 4X4TCKE29TK097079

Mileage: 0

Licence:

Invoice #:

Date In: 17 SEP 25

Promised:

Date Sched:

Completed: 30 SEP 25

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi.

CORRECTION: Brought camper in. Torqued lugg nuts to 110ft lbs. Brought all tires including spare to 65psi. Checked roof found voids pictures taken. Jacked both axels up to check breaks and ebreaks to be working. All clearnace and break lights working. Found voids on exterior of unit. Pured both lp tanks and filled. Went inside camper after connection to city water. Found scratch on freezer door of fridge. Cabinet door with holes all over it. Slideout has trouble going in and out. All plumbing works on city. Range fan works. Awning fabric im good condition and awning hardware works well. Microwave works, fridge works, all outlets work. Ac unit works. Furance and water heater work. Water pump works. City fill and fresh tank fill in good condition. Range top works. Tv anetna works at all three locations. Stablizer jacks work. Bunk room latch for top bunk holds. Both fold down couches work. Electric fire place works. Outside grill works. Unit passed lp drop test. Company decaladded. Black tank flush works. Control board and lights work on 12v. Outside light works drian valves work plumb traps work. Tank sensor read well.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	2.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: MANY VOIDS ON THE ROOF

CAUSE: Voids on roof

CORRECTION: During pdi noticed voids in dicor on roof as well as cracking in dicor around solar conection filled voids with dicor.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



Z990 MISC LABOUR CODE (EXTERNAL) CCV 37.00

Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: VOIDS AROUND THE SIDE OF THE UNIT

CAUSE: Multiple voids in unit exterior

CORRECTION: During pdi noticed mutiple voids are seals on exterior of unit. Ran clear silicone to seal voids

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #2: 37.00

Job #4 - Warranty

COMPLAINT: OUTSIDE SHOWER LEAKS

CAUSE: Outside shower leaking.

CORRECTION: Outside shower was leaking. Checked connections and they were lose at hot and cold and shower. Tightned all three and shower stopped leaking

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50

Subtotal for Job #4: 18.50

Job #5 - Warranty

COMPLAINT: BATHROOM DOOR DOESNT LATCH

CAUSE: Bathroom door will not latch

CORRECTION: During pdi noticed bathroom door was not latching. Too, screws out and pulled latch as far forward as possible. Door lat hes now.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #5: 37.00

Job #6 - Warranty

COMPLAINT: THE FRONT DOOR HAS A SCRATCH ON IT


CAUSE: Front door has scratch

CORRECTION: During pdi noticed front entry door has scratch on it. Parts request put in not replacing

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #6: 37.00

W/O: 77832



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 77832

Parts Total:	0.00
Labour Total:	166.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	166.50


Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Sep 2025

Customer Work Order



Customer #: 1000
BASDEN'S AMERICAN RV,

