

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77836
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11648 - 2026 COUGAR HALF-TON 29BHL 4YDFCGN26T2500867
VIN: 4YDFCGN26T2500867 HIN: SER#: 4YDFCGN26T2500867
Mileage: 0 Work Order Comp: 23 OCT 25
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 17 SEP 25 Inv #: 423539

WO # Job # Description JOB INFORMATION

77836 1 UNIT HAS WHAT APPEARS TO BE 2 SETS OF LOW POINT DRAINS AND ONE
SET HAS NO SHUT OFFS.
When running the city water and fresh tank pump, i noticed there
are a set of low point drain that dont have valeves on them. When
i try to run water through the water system, it comes out these 2
lines.
Recieved 2 shut-off valves from parts. Crimped both fittings on
hot and lines. Pressurized water system. The water system is now
working properly.
77836 3 THE LINO NEAR THE DINNETTE IS DAMAGED AND NEEDS FIXED
Linolium
Went to the house to find a piece of linolium to go under the
cabinets. Cut out linolium under sink. Glue new piece down. Layed
out and taped off replacement piece. Cut out and glued down.
77836 2 BACK SPLASH LOOSE
Backsplash is loose from the wall
Applied spray adhesive to the wall and secured the backsplash.

Part No Job# Description PARTS Qty Price Total

ESC30879 1 30879 Shut Off Valve; PEXLock; St 2.00 6.67 13.34
720182 3 S/O-Lino-Folded-48" x 109"-Birnam 0.00 79.76 0.00
767089 3 S/O-LINO 1.00 74.40 74.40

Claim : 77836

```

*****
Part No      Job#  Description      PARTS      Qty      Price      Total
*****

```

```

*****
Lab Code     Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990         1  MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990         1  MISCELLANEOUS REPAIR      0.40      180.00      72.00
Z990         3  MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990         3  MISCELLANEOUS REPAIR      0.06      180.00      10.80
Z990         3  MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990         3  MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990         3  MISCELLANEOUS REPAIR      0.04      180.00      7.20
Z990         3  MISCELLANEOUS REPAIR      0.40      180.00      72.00
Z990         3  MISCELLANEOUS REPAIR      0.00      180.00      0.00
Z990         3  MISCELLANEOUS REPAIR      0.70      180.00     126.00
Z990         2  MISCELLANEOUS REPAIR      0.10      180.00      18.00

```

```

*****
Excode      Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT         3  UPS-LINO          1.00      12.00      12.00

```

```

Parts Total:      87.74
Labour Total:     306.00
Sublet Total:      0.00
Extras Total:     12.00

```

>>>> Claim Total: 405.74

Customer Signature: _____

Date: _____