



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77957



CUSTOMER WORK ORDER

WO #: 77957 (Appointment Date: 06 OCT 2025 - Time: 04:30am)

Customer: 54780 - GILES, WENDY -
812-664-9768

Tag:

Author: GA

Location: 1015 CHECK PREAUTH

Stock #: 11569

Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 211BH

Chassis #: 5ZT2CAKB5SU045563

Serial #: 5ZT2CAKB5SU045563

Mileage:

Licence:

Invoice #:

Date In: 06 OCT 25

Promised:

Date Sched:

Completed: 10 OCT 25

Warr. Date: 15 APR 25

Job #1 - Warranty

COMPLAINT: VALANCE ABOVE THS DINNETTE FELL DOWN

CAUSE: Valance fell off

CORRECTION: Brought csmper in saw valance had fallen off. Saw mounting screws had been stripped. Grabbed bigger diameter wood screws to secure bracket in place. Adjusted blind because it was not level. Adjusted mounting brakect. Once adsjuted lined valance up and shoot screws to secure to bracket. Valance holds

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 37.00

Job #2 - Internal

COMPLAINT: LOOK AT THE JACKS CUSTOMER HAS TO KICK THEM TO COME DOWN

CAUSE: Jacks not working.

CORRECTION: Brought unit in. Connected to shore power. Ran jacks down and then back up. Disconnected from shore power. Ran of 12v both jacks went down. Ran multiple times on 12v. Extension and retraction. Jacks worked everytime. Could not recreate.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #2: 0.00

Customer #: 54780
GILES, WENDY



W/O: 77957

Parts Total:	0.00
Labour Total:	37.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	37.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Oct 2025

Customer Work
Order



Customer #: 54780
GILES, WENDY

