

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2479851
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CATB0TN302221
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	300 / 300
OWNER INFORMATION		ITEM #	CAT281QBUNK-8-300
ZACHARY P CAMPBELL		DEALER RO #	77998
6719 LAURA LANE		CLAIM START DATE	10/27/2025
Evansville, IN 47720		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	10/21/2025	WARRANTY EXPIRATION DATE	10/21/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-106-24-11-001253	Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-10-27 10:02:18 :: NO TANKS ARE WORKING ON THE PANEL Tank levels not showing up on control panel Took panel down and checked the wires that are going to the back of the tank level board all good there. So i took the underbelly down and checked the ground at the fresh tank and i wasn't getting anything there So i put a jumper wire from the ground wire to the frame and the tank levels worked as they should. So i made a ground wire and conected it to the ground wire and ran it to the frame and everything works properly now. Put the underbelly back up and control panel good to go			
Model#	Dlr Sub Hrs	1.50	Sub Labor Amt	\$277.50
Serial#	Appr Hrs	1.50	Appr Labor Amt	\$277.50
	Notes			
	AUTHORIZED AS REQUESTED			

Labor

Line# 2	Operation Code	Operational Description		
	40-106-24-11-001253	Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-10-27 10:03:09 :: INSTALL THE WIRING TO THE STAY JACKS Install wiring for stay jacks Had to drill hole i. Underbelly at front and back jacks to hook wires up. Ran wire from back to the front of the camper up in the Underbelly for the the jack switches that i have to mount in the front compartment. Then i had to run a power wire with a inline fuse to the battery to get power to the switches that i have to come up from the Underbelly between the wall for the switches mounted in front compartment. Got the switches and had to mount them a plastic case. Thaat i had to cut the holes in it for the switches, because they were deeper than the wall thickness. Ran the power wire with a fuse link in it from the battery and ran a designated ground wire from the switches to the battery that i attached to the main ground wire to make sure they connect it also. Tested both stabilizer jacks and they work properly. Its good to go			
Model#	Dlr Sub Hrs	7.00	Sub Labor Amt	\$1,295.00
Serial#	Appr Hrs	7.00	Appr Labor Amt	\$1,295.00
	Notes			
	AUTHORIZED AS REQUESTED			

Labor

Line# 3	Operation Code	Operational Description
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2025-10-27 10:03:47 :: WHEN THE PUMP IS ON THE LIGHTS FLICKER Lights flickering when water pump is running So after inspection of the water pump when running the lights flicker. I ran a jumper wire off the ground wire to the ground bus bar that fixed the problem. So i ran a new wire from the ground off the water pump to the ground bus bar and water pump works properly and lights dont	

flicker. Good to go

Model#

Dlr Sub Hrs

0.40

Sub Labor Amt \$74.00

Serial#

Appr Hrs

0.40

Appr Labor Amt \$74.00

Notes

AUTHORIZED AS REQUESTED

Submitted

Labor Amt

\$1,646.50

Parts & Freight

\$0.00

Total

\$1,646.50

Approved

Labor Amt

\$1,646.50

Parts & Freight

\$0.00

Total

\$1,646.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.