



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77998
Promised Date: 24 OCT 25

CUSTOMER WORK ORDER

WO #: 77998

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1030 CHECK WORK

Stock #: 11668
Stock Desc: 2026 TT COACHMEN
CATALINA 281QB
Chassis #: 5ZT2CATB0TN302221
Serial #: 5ZT2CATB0TN302221
Mileage: 0
Licence:

Invoice #:
Date In: 09 OCT 25
Promised: 31 OCT 25
Date Sched:
Completed: 27 OCT 25
Warr. Date: 21 OCT 25

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi
Trim

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Running lights and tail lights work properly brakes and Emergency Brakes work properly installed new battery box. Filled 2 20# lp tanks. Exterior inspection screen door latch needed adjusted and main door latch needed adjusted. Adjusted both doors and they both work properly now. Outdoor kitchen door had a rivet sticking out a little that made a scratch on the frame. So i took care of the rivet and covered up the scratch good now. Found a void in the sealer on running light door side that i fix with clear silicone. Exterior inspection looks good. Roof inspection looks good i did touch up back corner non door side with black dicor all good now and sideroom roof good. Stabilizer jacks have electric motors and wires are just tied up not ran to anything. Interior inspection did my lp drop test on outside port with stove and water heater running made a adjustment to regulator lp system works properly now. My fresh grey and black tanks are not registering on my control board. After tracing it down to a bad ground. So i ran a ground wire to the frame and tank levels work properly. Stove works properly microwave works properly both refrigerators work properly ac works properly furnace works properly water heater works properly all outlets work properly and USB ports work properly all windows and blinds work properly radio works properly tv antenna works properly. Hooked to city water and flushed out all the lines added water to fresh tank and ran water pump and flushed out all the lines water pump works properly. All the lights work properly. Bedroom door needed adjusted it shuts properly now. And made adjustment to bathroom door at the striker and it works properly now. Emptied black and grey tanks and fresh tank. A J wrap support was missing a screw so i got a new screw and secured it. Put trim on cabinet.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)		N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,



Job #1 - Warranty

COMPLAINT: NO TANKS ARE WORKING ON THE PANEL

CAUSE: Tank levels not showing up on control panel

CORRECTION: Took panel down and checked the wires that are going to the back of the tank level board all good there. So i took the underbelly down and checked the ground at the fresh tank and i wasn't getting anything there. So i put a jumper wire from the ground wire to the frame and the tank levels worked as they should. So i made a ground wire and connected it to the ground wire and ran it to the frame and everything works properly now. Put the underbelly back up and control panel good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50

Subtotal for Job #1: 277.50

Job #2 - Warranty

COMPLAINT: INSTALL THE WIRING TO THE STAY JACKS

CAUSE: Install wiring for stay jacks

CORRECTION: Had to drill hole i. Underbelly at front and back jacks to hook wires up. Ran wire from back to the front of the camper up in the Underbelly for the the jack switches that i have to mount in the front compartment. Then i had to run a power wire with a inline fuse to the battery to get power to the switches that i have to come up from the Underbelly between the wall for the switches mounted in front compartment. Got the switches and had to mount them a plastic case. Tha at i had to cut the holes in it for the switches, because they were deeper than the wall thickness. Ran the power wire with a fuse link in it from the battery and ran a designated ground wire from the switches to the battery that i attached to the main ground wire to make sure they connect it also. Tested both stabilizer jacks and they work properly. Its good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	647.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	462.50

Parts

Part #	Description	Qty	Price	Total
F100642174	JACK SWITCH	2.00	33.14	66.28
19-3535	Fuse Holder; ATO/ ATC Blade Fuses; 5	1.00	5.67	5.67

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- SWITCHES	1.00	13.61	13.61

Subtotal for Job #2: 1,380.56

Job #3 - Warranty

COMPLAINT: WHEN THE PUMP IS ON THE LIGHTS FLICKER

CAUSE: Lights flickering when water pump is running

CORRECTION: So after inspection of the water pump when running the lights flicker. I ran a jumper wire off the ground wire to the ground bus bar that fixed the problem. So i ran a new wire from the ground off the water pump to the ground bus bar and water pump works properly and lights dont flicker. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	74.00



Subtotal for Job #3: 74.00

W/O: 77998
Promised Date: 31 OCT 25

Parts Total: 71.95
Labour Total: 1,646.50
Sublet Total: 0.00
Extras Total: 13.61
WORK ORDER TOTAL: 1,732.06

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Oct 2025



Customer #: 1000
BASDEN'S AMERICAN RV,

