



Pre- Authorization number	PREAUTH293 75 (PA03923114)	Reference no.78005	Status	Approv ed
---------------------------------	----------------------------------	--------------------	--------	--------------

Root	Approved Actual				Base			
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
7301342A	KSB-210122 Bed-Slide Sidewall Crack	0	20	15		1	0	Complaint: FRONT SLIDE ROOM CRACKING LOOKING FOR RECALL OR TSB Cause: CHECKING FOR REPAIR Correction: CHECKING FOR REPAIR KRV- Approved to perform KSB repair sent to Dealer

Pre-Authorization number: PREAUTH29375 15

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.