

BASDEN RV CENTER, INC dba AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 78057
 MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
 Customer: 27089 - ALLEN DUKE
 Address: 7954 LYDDANE BRIDGE RD S OWENSBORO, KY

42301

Phone: 270-570-4799

Stock Number: 11579 - 2025 CATALINA SUMMIT SERIES 261BHS 5ZT2CARB1SU045761

VIN: 5ZT2CARB1SU045761 HIN: SER#: 5ZT2CARB1SU045761

Mileage: 0 Work Order Comp: 30 OCT 25

Auth. No: Dealer #:

Warr. Date: 12 APR 25 Work Order Date: 16 OCT 25 Inv #: 423916

| WO # | Job # | Description | JOB INFORMATION |
|-------|-------|--|-----------------|
| 78057 | 2 | LIGHT STRIPS ON FRONT OF CAMPER ARE COMING OUT OF THEIR TRACK ON BOTH SIDES Lights pulled from track. Doorside Accent Light was bubbled out in multiple spots. Attempted to put it back in track but its length it to long so i had to remove from track at the lowest bubbled spot and work light into track upward till excess reached the top end and cut about a half an inch off and sealed the end over with dicor. Light on the OffDoorSide was just out of track on on one side of light so i worked it back into the track. | |

| | | | |
|-------|---|--|--|
| 78057 | 3 | FABRIC ON VINYL FLOOR IN SLIDE ROOM IS COMING LOOSE Slide material under lip of slideroom vynle came loose. Cut some cardboard the length of slideroom and slide it u der the lip of Vynle slideroom floor and then pulled the slide material out as much as possible and sprayed the backside with 3M Adhesive and glued slide carpet back to the bottom sid3 of Vynle floor and stretched back into place. | |
|-------|---|--|--|

| Lab Code | Job# | Description | LABOUR | Hrs | Rate | Total |
|----------|------|-----------------------------|--------|------|--------|-------|
| Z990 | 2 | MISC LABOUR CODE (EXTERNAL) | | 0.20 | 185.00 | 37.00 |
| Z990 | 3 | MISC LABOUR CODE (EXTERNAL) | | 0.30 | 185.00 | 55.50 |

Parts Total: 0.00
 Labour Total: 92.50
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 92.50

Customer Signature: _____

Date: _____

Claim : 78057

```
*****  
Lab Code Job# Description LABOUR Hrs Rate Total  
*****
```