



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78104
Promised Date:
21 OCT 25

CUSTOMER WORK ORDER

WO #: 78104 (Appointment Date: 21 OCT 2025 - Time: 02:30pm)

Customer: 56252 - BREITWEISER,
MICHAEL - 812-351-1712

Tag:

Author: BH

Location: 1110 CHECK WORK

Stock #: 11442

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT 231MKS

Chassis #: 5ZT2CAMB8SU044310

Serial #: 5ZT2CAMB8SU044310

Mileage: 0

Licence:

Invoice #:

Date In: 21 OCT 25

Promised: 31 OCT 25

Date Sched:

Completed: 08 NOV 25

Warr. Date: 07 OCT 25

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE ALL TREAD IS BENT ON BOTH REAR STABILIZER JACKS.

CAUSE: Rear stabilizer jack bent

CORRECTION: Inspection of the rear stab jacks found that the screw rod is bent that moves the jack up and down. Put a parts request in for two new jacks

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	74.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
C01283376	JACK, SCISSOR BEARCLAW 24" 5000# W/S	2.00	32.71	65.42

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	44.37	44.37

Subtotal for Job #1: 183.79

Job #2 - Internal

COMPLAINT: CUSTOMER ADVISES THERE IS A SLOW DRIP FROM THE BLACK TANK AT THE DUMP VALVE. CUSTOMER WAS NOT ON SEWER AND KNIFE VALVE WAS CLOSED.

CAUSE: Water getting by knife valve on black tank

CORRECTION: Hooked to city water and 2/3 in black tank and let it sit for 10 minutes and no water go by knife valve. Couldn't replicate

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THERE ARE SOME VOIDS IN SILICONE ON ONE SIDE OF THE SLIDE AND AROUND SOME OF WINDOWS. AND THE REAR TOP

CAUSE: Voids in sealer

Customer #: 56252
BREITWEISER, MICHAEL



CORRECTION: Touched up the spots pointed out with clear silicone. And checked over the camper. All good now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Subtotal for Job #3: 37.00

Job #6 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT EITHER THE DECAL OR THE PAINT TO THE LEFT OF THE STORAGE COMPARTMENT ON THE OFF DOOR IS PEELING.

CAUSE: Decal torn and air bubble

CORRECTION: After inspection of the decal seen that it is tore in two spots. Put in a parts request

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	74.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
F100418579	GRAPHIC, #14 ODS "CATALINA" LOGO 202	1.00	11.54	11.54

Subtotal for Job #6: 85.54

Job #4 - Warranty

COMPLAINT: WHEN TRAVELING THE BATHROOM DOOR OPENS THIS IS THE INSIDE DOOR NOT THE OUTSIDE DOOR

CAUSE: Bathdoor open during transport

CORRECTION: Put shims behind hinges to move door latch more in the striker. So it dont flex and come out

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Subtotal for Job #4: 55.50

Parts Total: 76.96
Labour Total: 240.50
Sublet Total: 0.00
Extras Total: 44.37
WORK ORDER TOTAL: 361.83

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 08 Nov 2025

W/O: 78104
Promised Date: 31 OCT 25



Customer #: 56252
BREITWEISER, MICHAEL

