



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 78127  
Promised Date:  
24 OCT 25

## CUSTOMER WORK ORDER

WO #: 78127

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 1117 CHECK PREAUTH

Stock #: 11573  
Stock Desc: 2025 TT COACHMEN  
CATALINA 243RBSLE  
Chassis #: 5ZT2CANB6SN301263  
Serial #: 5ZT2CANB6SN301263  
Mileage: 0  
Licence:

Invoice #:  
Date In: 23 OCT 25  
Promised: 31 OCT 25  
Date Sched:  
Completed: 17 NOV 25  
Warr. Date:

### Job #24V264 - Warranty

COMPLAINT: 25V264, 2025-217 - INCORRECT OVER CURRENT PROTECTION The front exterior accent lamp wire (16AWG) may be on a 30AMP breaker, whereas it should be on a 10AMP over current device. The awning may be missing the required 15AMP over current protection. The auto-leveling system may be wired to constant hot on a 30AMP mini-breaker.

CAUSE: 3 recalls

CORRECTION: 2 mini breakers tied together with copper buss bar is in underbelly so self leveling is correct. Awning needed the 15A inline fuse installed which i did at distribution panel. Accent lights in front needed a 10A fuse installed which i did at the switch in the compartment.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK      | 99.90 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK      | 5.55  |
| Z990 | MISC LABOUR CODE (EXTERNAL) | JRK      | 33.30 |

### Parts

| Part #  | Description                          | Qty  | Price | Total |
|---------|--------------------------------------|------|-------|-------|
| 19-3535 | Fuse Holder; ATO/ ATC Blade Fuses; 5 | 2.00 | 5.67  | 11.34 |

**Subtotal for Job #24V264: 150.09**

Parts Total: 11.34  
Labour Total: 138.75  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 150.09**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 17 Nov 2025



Customer #: 1000  
BASDEN'S AMERICAN RV,

