



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 78475



## CUSTOMER WORK ORDER

WO #: 78475 (Appointment Date: 15 NOV 2025 - Time: 11:00am)

Customer: 56066 - BEMONT, KATHLEEN Stock #:

- Stock Desc: 2026 TT FOREST RIVER  
Tag: CAMPSIGHT

Author: GA

Location: 1121 CHECK STATUS WITH  
ZS

Chassis #:  
Serial #: 5ZT2CRRB7TF081717

Mileage:

Licence:

Invoice #: 424563

Date In: 15 NOV 25

Promised:

Date Sched:

Completed: 19 NOV 25

Warr. Date:

### Job #1 - External

COMPLAINT: CAMPER HAS A LEAK UNDER THE CAMPER CUSTOMER PULLED OUT AND SAW WATER FALLING FROM UNDER THE CAMPER

CAUSE: Ran water through all lines and fixtures. The water lines and plumbing lines were also tested during the other jobs. I didn't see any signs of a leak. I believe the water was from the black tank flush/vacuum breaker leaking.

CORRECTION: The vacuum breaker and the lines leaking were the only leaks found. This was repaired in the other job.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |

Subtotal for Job #1: 0.00

### Job #2 - Warranty

COMPLAINT: SMALL LEAK UNDER THE BACK THE BATH ROOM  
SINK AT VACUUM BREAKER

CAUSE: The inlet to the vacuum breaker is missing the gasket screen on the outside. Hooked up the water hose and ran water through the vacuum. Both ends of the breaker are leaking and it is leaking internally.

CORRECTION: Replaced outside the gasket screen. The supply line is has different cone washers that the rest of the unit. Replaced the supply line with a new hose that has the " normal" cone washers installed. The replacement vacuum breaker is leaking internally. Went to another style of vacuum breaker. Tested and secured the vacuum breaker to the wall. All leaks have been fixed. Cleaned up area.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 55.50 |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 0.00  |

### Parts

| Part #    | Description                      | Qty  | Price | Total |
|-----------|----------------------------------|------|-------|-------|
| 10-7150   | CONE WASHER SWIVEL SEAL          | 1.00 | 0.23  | 0.23  |
| BRV113704 | FITTING-RISER W/SWIVEL ELBOWS    | 1.00 | 8.15  | 8.15  |
| 10-1211   | 20183 3-PK 1" HOSE FILTERS       | 1.00 | 3.95  | 3.95  |
| 23-0328   | VACUUM BREAKER                   | 1.00 | 17.33 | 17.33 |
| 681487    | 1/2" BARB X 1/2 FPT SWIVEL CONE  | 1.00 | 2.24  | 2.24  |
| 282770    | 94239 VACUUM BREAKER/CHECK VALVE | 1.00 | 22.62 | 22.62 |

Customer #: 56066  
BEMONT, KATHLEEN



Subtotal for Job #2: 110.02

**Job #3 - External**

COMPLAINT: THE TANKLESS WATER HEATER ONLY WORKS IN THE BATHROOM SINK MIGHT NOT BE FLOWING RIGHT

CAUSE: Hooked up to city water. Turned on l.p. tank. Ran water through all of the fixtures inside and outside of the unit for several minutes. All of the fixtures have hot water flowing through them.

CORRECTION: No correction. Could not replicate the issue stated.

**Labor**

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |

Subtotal for Job #3: 0.00

**Job #WINTER - External**

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: winterize

CORRECTION: pulled unit into shop. located pump. bypassed and drained water heater. ran a.f. through all lines and fixtures. drained all tanks. parked unit.

**Labor**

| Code | Description    | Mechanic | Total |
|------|----------------|----------|-------|
| Z990 | WINTERIZE UNIT | ZMS      | N/C   |

**Parts**

| Part # | Description               | Qty  | Price | Total |
|--------|---------------------------|------|-------|-------|
| 24181  | -50 RV ANTI-FREEZE GALLON | 3.00 | N/C   | N/C   |

**Other Services**

| Code | Description   | Qty  | Price | Total |
|------|---------------|------|-------|-------|
| SS   | SHOP SUPPLIES | 1.00 | N/C   | N/C   |

Subtotal for Job #WINTER: 0.00

|                          |               |
|--------------------------|---------------|
| Parts Total:             | 54.52         |
| Labour Total:            | 55.50         |
| Sublet Total:            | 0.00          |
| Extras Total:            | 0.00          |
| <b>WORK ORDER TOTAL:</b> | <b>110.02</b> |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 25 Nov 2025

W/O: 78475



Customer #: 56066  
BEIMONT, KATHLEEN

