



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 78536



### CUSTOMER WORK ORDER

WO #: 78536

Customer: 21435 - EDWARDS, JAMES  
R. - 812-309-0641  
Tag:  
Author: BH  
Location: 1205 CHECK DELIVERY

Stock #: 11678  
Stock Desc: 2026 5W KEYSTONE  
COUGAR HALF-TON 26RKE  
Chassis #: 4YDFCGM2XTV503559  
Serial #: 4YDFCGM2XTV503559  
Mileage:  
Licence:

Invoice #:  
Date In: 21 NOV 25  
Promised:  
Date Sched:  
Completed: 30 NOV 25  
Warr. Date: 05 DEC 25

#### Job #1 - Internal

COMPLAINT: ADD DUCKED 18K CHILL CUBE IN BEDROOM

CAUSE: Install front ac

CORRECTION: Had to get dicor off the screws to remove vent. Then i cleaned off all the dicor so the surface was nice and flat. Took roof tape to cover the screw holes from the roof vent. Put the roof unit in its space. Went inside and found my power source for the ac unit. Hooked up the wires. Tightened down the ac unit taped off everything except for the duct work. And then i made sure that the cold air couldn't get to the front of the ac. Conected the connectors from the control panel to the AC unit made sure all the screws were tight and tested it. A c works properly and mounted the remote control on the wall

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

#### Parts

Part #	Description	Qty	Price	Total
10518	18K BLK DUCTED CHILL CUBE	1.00	N/C	N/C
10526	FURRIION CHILL CUBE DUCTED ADB	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

#### Job #2 - Internal

COMPLAINT: SWAP TPMS FROM TRADE

CAUSE: Swap TPS from trade-in to new unit  
Swap Chevrolet factory trailer TPMS sensors from trade to new unit.

CORRECTION: Swapped TPS from Trade-in to new unit.  
I removed the wheels on both campers. I had to break down the wheels and tires on both the new trailer and the old trailer. Install new valve stems on the old trailer and used the old factory Chevrolet trailer valve stems on the new trailer wheels. No new valve stem seals were supplied. Reinstalled all of the wheels on both units.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

**Subtotal for Job #2: 0.00**

#### Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL



Customer #: 21435  
EDWARDS, JAMES R.



CAUSE: Pdi

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Air pressure correct in all 5 tires. Running lights and tail lights work properly brakes and Emergency Brakes work properly it had factory installed batteries. 4 way hook up works properly on the back. Filled 2 30# lp tanks. One would not fill so i had to get a new one. Auto leveling works properly.

Exterior inspection looks good now i had to adjust the striker on the entry door and the stairs bothe good now. Roof inspection found a couple voids that I sealed with dicor self-leveling roof good now. Both awnings work properly and fabric is good. Interior inspection hooked up to city water and flushed out all the lines. With no leaks. Stove works properly microwave works properly both refrigerators work properly ac works properly furnace works properly water heater works. Both tvs work and antenna properly. Fireplace works properly. All the outlets work properly and USB ports work properly. All the doors and cabinets doors work properly except the bedroom cabinet door hit each other. I have to adjust. They work properly now. Put water in fresh tank and ran the water pump and flushed out all the lines. Water pump works properly remotes for Fireplace and TV are behind tv. Outside tv is to the right of tv on the wall. Did my lp drop test on outside port with stove and furnace running. Made a small adjustment to the regulator. System works properly now. Got the new ac installed on front and it works properly. Drained black tank and gray tanks and fresh tank. Unit is good to go

**Labor**

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

**Subtotal for Job #PDINFW: 0.00**

**Job #FPDINFW - Internal**

COMPLAINT: FINAL PDI ON NEW FIFTH WHEELS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly 4 way on back works properly. Exterior inspection looks good. Roof inspection looks good. Interior inspection looks good and all the appliances are working properly. Both ac works properly furnace works properly. I just did the pdi on this unit.

**Labor**

Code	Description	Mechanic	Total
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL)	JTW	N/C

**Parts**

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

**Subtotal for Job #FPDINFW: 0.00**

**Job #3 - Warranty**

COMPLAINT: LP TANK WILL NOT FILL

CAUSE: Lp tank no fill



CORRECTION: Took both 30# lp tanks out to fill and one filled and the other one didn't. I tried about 4 times. So i got a new 30# lp tank and it filled. So unit has 2 30# full lp tanks now

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	36.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
66-4907	L.P.CYLINDER 30 LB. PW	1.00	103.88	103.88

**Subtotal for Job #3: 139.88**

**Job #4 - Warranty**

COMPLAINT: OUTLETS IN THE DS SLIDE ROOM DO NOT HAVE POWER

CAUSE: Gfci would not work i slideroom

CORRECTION: Inspection of the gfci outlet in the slideroom door side. Took side panel off inside outdoor kitchen area and looked at the wires and started checking them and one of the big connectors not plugged in. Turn power off to unit and plugged the connector together and then i put power to unit and that fixed the problem. Good to go now

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	54.00

**Subtotal for Job #4: 54.00**

**Job #5 - Warranty**

COMPLAINT: IN THE BED ROOM THE WASHER AND DRYER DOORS RUB AND NEEDS ADJUSTED

CAUSE: Door hitting in the middle and not closing

CORRECTION: I had to adjust the hinges on both doors to get them to shut without hitting. They work properly now

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	36.00

**Subtotal for Job #5: 36.00**

**Job #WINTER - Internal**

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: Winterize unit

CORRECTION: Turned valves to winterize mode. And ran 2 gallons through the pump. Started at the kitchen faucet and ran cold and hot until solution was there. Then repeated it for the bathroom faucet and shower and toilet and washer hook up and outside shower. Then poured solution in the drains. Drained black tank and gray tanks and fresh tank and water heater. And then cleaned up my mess

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C

<b>Parts</b>				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	4.00	N/C	N/C



Customer #: 21435  
EDWARDS, JAMES R.



**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #WINTER: 0.00**

Parts Total: 103.88  
Labour Total: 126.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 229.88**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 05 Dec 2025

Customer Work Order

W/O: 78536



Customer #: 21435  
EDWARDS, JAMES R.

