



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78681
Promised Date:
20 DEC 25



Customer #: 55633
DEATON, DANIEL



CUSTOMER WORK ORDER

WO #: 78681

Customer: 55633 - DEATON, DANIEL -
(270) 313-0943

Tag:

Author: BH

Location: 0109 CHECK PREAUTH

Stock #: 11632

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT 134BHX

Chassis #: 5ZT2CABC4SK011599

Serial #: 5ZT2CABC4SK011599

Mileage: 0

Licence:

Invoice #:

Date In: 11 DEC 25

Promised: 20 DEC 25

Date Sched:

Completed: 31 DEC 25

Warr. Date: 20 DEC 25

Job #FPDINTT - Internal

FINAL PDI ON NEW TRAVEL TRAILERS

Labor Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

SWAP CUSTOMER'S HITCHWORK

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned water heater bypass on. Turned the valve at the water pump to winterize mode. Pumped 2 gallons of winterize solution through to the bathroom shower cold and hot then repeated for toilet and kitchen faucet and depressed city water inlet. Drained black tank and gray tank and fresh tank. Then poured solution down drains. Good to go

Labor





Code	Description	Mechanic	Total	
Z990	WINTERIZE UNIT	JTW	N/C	
Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: INSERT TRIM IS SHRUNK AND NEEDS REPLACED

CAUSE: Vinyl insert was too short.

CORRECTION: During my exterior inspection I found that the vinyl insert across the back was too short. So i put a new piece in it. Good to go

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	46.25
Parts				
Part #	Description	Qty	Price	Total
E369	E369 BLACK HD 1" x 25' INSERT TRIM	1.00	12.31	12.31
Subtotal for Job #1:				58.56

Job #2 - Internal

COMPLAINT: RESEALTHE WINDOWS AND ROOF

CAUSE: Voids in the sealer

CORRECTION: During my roof inspection and exterior inspection i found several voids in the sealer that I filled with dicor self-leveling and black Dicor and silicone. All good now

Labor			
Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Subtotal for Job #2:			0.00

Job #3 - Warranty

COMPLAINT: LP WILL NOT ADJUST OUT DURING DROP TEST. MATT APPROVED.

CAUSE: Lp regulator can't adjusted

CORRECTION: On doing my lp drop test there wasn't any adjustment in the regulator it was bottomed out. So i put and new one on it. Once I installed a new regulator i leak check my connections. No leaks and it works properly now

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	92.50
Parts				
Part #	Description	Qty	Price	Total
06-0445	MEGR-291P LP REGULATOR	1.00	54.12	54.12



W/O: 78681
Promised Date: 20 DEC 25



Customer #: 55633
DEATON, DANIEL



Subtotal for Job #3: 146.62

Job #4 - Internal
PER DREW LP TANK COVER

Parts				
Part #	Description	Qty	Price	Total
40565	40565 BLK 20# SINGLE TANK COVER	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Parts Total: 66.43
Labour Total: 138.75
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 205.18

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 06 Jan 2026

Customer Signature : _____

