



Pre- Authorization number	PRAUTH531 89 (PA03946155	Reference no.78691	Status	Approv ed
---------------------------------	--------------------------------	--------------------	--------	--------------

Root		Approved			Actual	Base	
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours
2302202B	Compartment Door	0	1.2	1		1	0.5
							Complaint: NON DOOR SIDE COMPARTMENT WITH WATER CONNECTION IS LOOSE Cause: Compartment door is loose where track attaches to door itself. Door measuring 32.25in wide, 28in tall. Putting in part request for new door and decal. Correction: REPLACE THE DOOR WITH DECAL Door measuring 32.25in wide, 28in tall. Putting in part request for new door and decal. KRV- VCB approve to replace door and decal

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.