



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78708
Promised Date: 24 DEC 25

CUSTOMER WORK ORDER

WO #: 78708

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 0114 BH TO CLSOE

Stock #: 11636
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE WOLF PUP 17SC
Chassis #: 5ZT2CKFC5TY039054
Serial #: 5ZT2CKFC5TY039054
Mileage: 0
Licence:

Invoice #:
Date In: 17 DEC 25
Promised: 31 DEC 25
Date Sched:
Completed: 15 JAN 26
Warr. Date:

Job #1 - Internal

COMPLAINT: ENTRY DOOR ON THE TOP RUBBS AND HARD TO OPEN

CAUSE: The door is hitting the frame trim on the outside. The door seal is torn at the top.

CORRECTION: Moved the trim over with a hammer to clear the door. The seal will need replaced.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
F100263737	ENTRY DOOR PART: RUBBER D-SEAL, .630	12.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: OUTDOOR SPEAKERS BROKEN FROM INSTALL SCREWS WERE TOO TIGHT

CAUSE: The plastic housing on both speakers are cracked. Needs replaced.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
F100141435	SPEAKER, DRIVEN 5.25" EXTERIOR BLACK	2.00	8.39	16.78
500627	CLEAR SIKASIL PLUS	1.00	10.87	10.87

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SPEAKER	1.00	32.09	32.09

Subtotal for Job #2: 133.74



Customer #: 1000
BASDENS AMERICAN RV,





Job #3 - Warranty

COMPLAINT: DOOR SIDDE WINDOW GIMP IS LOOSE

CAUSE: The corner of the window gimp is damaged and needs replaced.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	25.90
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	29.60

Parts

Part #	Description	Qty	Price	Total
213162	RV08523-03 GLAZING BEAD SOLD BY INCH	84.00	0.16	13.44

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-WINDOW SEAL	1.00	15.83	15.83

Subtotal for Job #3: 84.77

Job #4 - Warranty

COMPLAINT: SLIDE OUT COMPARTMENT DOOR RUBS

CAUSE: The door is hitting the frame.

CORRECTION: Took a hammer and a block of wood and moved the frame from the door and the hinge away from the frame. The door now clears.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Subtotal for Job #4: 37.00

Job #5 - Warranty

COMPLAINT: BATHROOM CABINET DOORS RUB

CAUSE: The doors are rubbing.

CORRECTION: Took a hammer and pushed the doors away from each other.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	18.50

Subtotal for Job #5: 18.50

Job #6 - Warranty

COMPLAINT: BEDROOM EGRESS SHADE WONT STAY UP

CAUSE: Window shade is not under proper tension.

CORRECTION: Tightened the strings to hold the shade up.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Subtotal for Job #6: 37.00

Job #7 - Internal

COMPLAINT: ANTIFREEZE BEHIND TOILET LEAKS?

CAUSE: There's a.f. on the floor u der the water line for the toilet.



CORRECTION: Located the water pump and placed a jug of a.f. on the winterize line. Pressurized water system and ran a.f. through the toilet. I didn't see any signs of a leak but i tightened the fitting on the valve. Cleaned up the floor.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #7: 0.00

Parts Total: 41.09
Labour Total: 222.00
Sublet Total: 0.00
Extras Total: 47.92
WORK ORDER TOTAL: 311.01

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Jan 2026

W/O: 78708
Promised Date: 31 DEC 25



Customer #: 1000
BASDENS AMERICAN RV,

