



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH580 Reference no.78732 35 (PA03950881)	Status	Approved
--------------------------	---	--------	----------

Servicing Dealer 1194 **Name** Basden's American RV **Address** 600 E Baseline Rd
Evansville, IN 47725 **VIN** 4YDF1PR29SF815217 **Retail sold on** 7/12/2025

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root	Operation Description	Sublet	Sub Hours	Approved Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
4122115B	Furnace - Suburban - Blower Wheel	0	1.8	1	1	1	0.4	<p>Complaint: FURNACE VENT RATTLES. CUSTOMER THINKS THE FAN ISN'T TURNING FREELY</p> <p>Cause: Blower fan for the exhaust was not tighten to the motor</p> <p>Correction: Turned on the furnace then heard a rattle from the furnace. Turned off the furnace. Unscrewed the exterior cover to the furnace then disconnected the lp line and power to the furnace. Disconnected the furnace vent hoses. Pulled out the furnace to inspect. Disassembled the cover to the blower motor, found the little blower fan to the exhaust side was loose. Tightened the set screw and put the cover back on the blower motor. Check for clearance in the blower fan. Assembled the furnace and put it back in the camper. Connected the furnace vents, lp line and power. Tested the furnace again and it was quiet. Put the exterior cover back on.</p> <p>KRV – REPAIR ONLY approved. KRV - VCB</p>
5104602B	Light, Porch or Hitch	0	0.2	0.2	1	1	0.2	<p>Complaint: SIDE LIGHT BY BOTTOM OF STEPS ISN'T WORKING</p> <p>Cause: LIGHT FAILED</p> <p>Correction: Pushed out the light from the j wrap then disconnected the light. Got a new light. Connected the new light and pushed it into the j wrap. Tested the light.</p> <p>KRV-approved to replace light KRV - VCB KRV - Please retain part for possible return or additional photos. Keystone will notify you within 48 hours of submitting your claim for disposition of the part</p>

Pre-Authorization number: PREAUTH58035

1.2

For paper claims only use one pre-authorization number per warranty claim form.
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.