

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2540052
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAVB4SX033236
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	205 / 205
		ITEM #	ACAT303RKDSLE
		DEALER RO #	78748
		CLAIM START DATE	01/02/2026
		CLAIM END DATE	01/01/1900
Labor rate: \$185.00			
OWNER INFORMATION			
MARK A MARTIN			
12256 S 525 W			
Cynthiana, IN 47612			
USA			
Retail Date of Purchase 02/28/2025		WARRANTY EXPIRATION DATE 02/28/2026	

Claim Line Details

Labor

Line# 1	Operation Code 20-46-01-13-000730	Operational Description Window Glazing, Seal - Exterior/Windows/Replace/Visibility	
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2026-01-02 12:23:38 :: PART OF THE WINDOW GASKET/ GLAZING IS HANGING LOOSE ON THE EXTERIOR SIDE OF THE COUCH SLIDE FRONT WINDOW. Fix window glazing Window glazing had come loose on window. Placed glazing back i to track. Noticed slideroom looks to be too close to front of unit and needs to move over or window glazing will keep coming loose when getting caught on flap seal. Pictures taken of flap seal. Waiting for aproval to adjust slideroom.			
Model#	Dlr Sub Hrs 0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs 0.30	Appr Labor Amt	\$55.50
Notes			

Labor

Line# 2	Operation Code 10-13-02-00-000211	Operational Description Slide Out Room - Frame & Chassis/Slide Out System/Adjust/No Tread Code	
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2026-01-05 10:37:24 :: SLIDE ROOM DOES NOT LOOK ADJUSTED Slideroom needs adjusted. Brought unit in. Noticed when fixing glazzing that slideroom was shifted to far over toward front cap. Loosed adjustments on arms of slideroom. Pushed room over toward front cap to pull in to back side of unit. Ran room in and out mulitple times and only got half inch of movement. When feeling inside of room cut out was short. No further adjustment possible.			
Model#	Dlr Sub Hrs 0.75	Sub Labor Amt	\$138.75
Serial#	Appr Hrs 0.75	Appr Labor Amt	\$138.75
Notes AUTHORIZED AS REQUESTED			

Submitted	Labor Amt	\$194.25	Approved	Labor Amt	\$194.25
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$194.25		Total	\$194.25

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____

SIGNATURE _____

All repairs described have been inspected and are satisfactory.

DATE _____