

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78839
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11600 - 2025 COUGAR HALF-TON 25MLE 4YDTCGM20SV506469
VIN: 4YDTCGM20SV506469 HIN: SER#: 4YDTCGM20SV506469
Mileage: 0 Work Order Comp: 31 JAN 26
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 16 JAN 26 Inv #: 426277

WO # Job # Description JOB INFORMATION

78839 1 LP COVER SCREWS FELL OUT AND MISSING THE NUTS THAT HOLD THE TOP
Screws missing in a top of 1 p cover
Took old cover off, replaced it with a new cover installed.The
boatTook old cover off, replaced it with a new cover installed.
The boats tightened the boats up good to go.

78839 2 THE BACKSPLASH OVER THE COUNTER TOP IN FRONT OF THE MAIN DOOR IS
COMING OFF THE WALL
Backsplash coming off the wall
Backsplash coming off the wall. Took the receptacle out and the
light off. The backsplash was only held to the wall about 2
inches. So i sprayed adhesive on the back of the back splash and
pressed it back up and put the light back up and the receptacle
and put clear silicone up the edge to hold the trim on. Good to
go

78839 3 LED STRIP OVER THE KITCHEN AREA TOO LONG AND HANGING DOWN IN THE
CORNER
Led strip light hanging down
Put some glue on the back of the light strip to hold it up. Good
to go now

78839 4 ADJUST THE ENTRY DOOR
Adjust entry door
After inspection of the door i found that the striker needed
adjustment. Once i adjusted the striker the door shuts properly.

Good to go

Lab Code	Job#	Description	LABOUR	Hrs	Rate

Z990	1	MISCELLANEOUS	REPAIR	0.10	180.00
Z990	1	MISCELLANEOUS	REPAIR	0.00	180.00
Z990	2	MISCELLANEOUS	REPAIR	0.20	180.00
Z990	3	MISCELLANEOUS	REPAIR	0.30	180.00
Z990	4	MISCELLANEOUS	REPAIR	0.30	180.00
				Total	

Parts Total:	13.84
Labour Total:	162.00
Sublet Total:	0.00
Extras Total:	12.10

Date: _____