



Pre-Authorization

Pre-Authorization number	PREAUTH63911 (PA03956540)	Reference no.	78839	Status	Approved
--------------------------	---------------------------	---------------	-------	--------	----------

Servicing Dealer	1194	Name	Basden's American RV	Address	600 E Baseline Rd Evansville, IN 47725	VIN	4YDTCGM20SV506469	Retail sold on
------------------	------	------	----------------------	---------	---	-----	-------------------	----------------

Root		Approved		Actual				
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	Base hours	Complaint/Cause/Correction
6200506B	LP Bottle Cover - Replace	0	0.1	0.1		1	0.3	Complaint: LP COVER SCREWS FELL OUT AND MISSING THE NUTS THAT HOLD THE TOP Cause: PARTS MISSING Correction: INSTALL NUTS AND BOLTS
3401203A	Backsplash - Kitchen Countertop	0	0.2	0.2		1	0.1	Complaint: THE BACKSPLASH OVER THE COUNTER TOP IN FRONT OF THE MAIN DOOR IS COMING OFF THE WALL Cause: Backsplash coming off the wall Correction: Backsplash coming off the wall. Took the receptacle out and the light off. The backsplash was only held to the wall about 2 inches. So i sprayed adhesive on the back of the back splash and pressed it back up and put the light back up and the receptacle and put clear silicone up the edge to hold the trim on. Good to go
5102808A	Light, LED-Striplight	0	0.3	0.3		1	0.3	Complaint: LED STRIP OVER THE KITCHEN AREA TOO LONG AND HANGING DOWN IN THE CORNER Cause: Led strip light hanging down Correction: Put some glue on the back of the light strip to hold it up. Good to go now
2300102A	Entrance Door - Hinged - Repair	0	0.3	0.3		1	0.2	Complaint: ADJUST THE ENTRY DOOR Cause: Adjust entry door Correction: After inspection of the door i found that the striker needed adjustment. Once i adjusted the striker the door shuts properly. Good to go
Pre-Authorization number: PREAUTH63911				0.9				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.