

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78872
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 2603R - 2026 FREELANDER 27QB 1FDWE3FN7SDD32380

VIN: 1FDWE3FN7SDD32380 HIN: SER#: 1FDWE3FN7SDD32380

Mileage: 3322 Work Order Comp: 11 FEB 26

Auth. No: Dealer #:

Warr. Date: Work Order Date: 21 JAN 26 Inv #: 426385

WO # Job # Description JOB INFORMATION

78872 1 RECALL 25V486 FR # 51-1955

Recall

Brought unit in. Followed recall protical. Parts request submitted for recall

78872 3 USB CHARGER BY DOOR IS NOT WORKING

Usb charger

Brought unit in tested usb chatger and had no power coming to charger. Paetd request submitted for usb charger

78872 4 HOLE IN FRONT PANEL OF BED. MUST OF BEEN NOTED ON DAF - THERE IS BLUE TAPE NEAR IT.

Bed panel

Brought unit in. Found hole in bed panel. Parts request submitted for panel and sesm tape

78872 5 TV IS RUBBING ON CEILING WILL NOT CLOSE FLUSH AGAINST WALL.

Tv

Brought unit in. Checked tv and it is not locking all ghe way in place. Noticed its missing a turn handle to secure it in place on tv bracket parts request submitted

78872 8 LP SAFETY CHECK

Lp test

Starting pressure was 13.5iwc. At 50% with furnace and range is 11iwc. Lock up stops at 13iwc. Fornleak test ran at 8iwc for

Claim : 78872

 WO # Job # Description JOB INFORMATION

 5mins. Had a leak during test. Checked at water heater, furnace, and range for leak. None found. Testing at range to check for leak. After checking and capping all appliances besides range. And spraying manifold and lines sprayed at regulator and found vent was leaking. Removed lp line from regulator. Removed regulator from tank and took to vise to remove adapter. Once removed placed lp thread tape on and placed adapter on new regulator. Went to unit and put thread tape on lp line. Attached lp line to regulator and then to tank. Attached all lp lines back to appliances and turned tank on and checked for leaks. Ran new lp test. Starting pressure was 11.5iwc. 50% with range and furnace is 10iwc. Adjusted to 11. Lock up pressure stops at 13.5iwc. Running leak test at 8 for 5mins. Unit passed leak test. No new leaks found

78872 2 BLACK TANK HEATER IS COMING LOOSE
 Tank heater
 Brought unit in. Saw black tank heater was falling off of unit. Cleaned area with mineral spirits and dried off. Then applied tape prime to both areas and used a piece of wood and jack to put pressure on spot while tape prime sets in to stick back to heater. Removed jack from wood holding tank heater up. Tank heater is sticking to tank

Part No	Job#	Description	PARTS	Qty	Price	Total
F100231286	1	32" FUEL LINE RECALL KIT		1.00	40.95	40.95
F100462835	3	Black Dual USB-A 2.4 AMP & 3.0 AM		1.00	19.96	19.96
F100320274	4	TAPE, SEAM VINYL 1" FAWN MAPLE		10.00	0.17	1.70
F100403479	4	LAUAN, 1/8" X 48" X 96" VERTICAL		1.00	61.87	61.87
C01219388	5	BLACK ADJUSTMENT KNOB FOR PIVOTIN		1.00	8.05	8.05
06-0450	8	MEGR-298P REGULATOR		1.00	56.41	56.41
C01228791	8	REGULATOR, 2-STAGE ASME W/POL BRA		1.00	37.45	37.45

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		1.00	185.00	185.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		1.50	185.00	277.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50

Claim : 78872

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990      8    MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990      8    MISC LABOUR CODE (EXTERNAL)      0.50     185.00     92.50
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.20     185.00     37.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT       1    UPS-QUICK CONNECT      1.00     16.30     16.30
FRT       3    UPS FREIGHT - JOBS 3,4,5,8      1.00    144.31    144.31

```

```

Parts Total:      226.39
Labour Total:     647.50
Sublet Total:      0.00
Extras Total:     160.61

```

>>>> Claim Total: 1,034.50

Customer Signature: _____

Date: _____