



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78872
Promised Date:
28 FEB 26

CUSTOMER WORK ORDER

WO #: 78872

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag:

Author: BH

Location: 0216 LAST CHUBBY TICKET
NEEDING PARTS

Stock #: 2603R

Stock Desc: 2026 C COACHMEN
FREELANDER 27QB

Chassis #: 1FDWE3FN7SDD32380

Serial #: 1FDWE3FN7SDD32380

Mileage: 3322

Licence:

Invoice #:

Date In: 21 JAN 26

Promised: 28 FEB 26

Date Sched:

Completed: 11 FEB 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: RECALL 25V486 FR # 51-1955

CAUSE: Recall

CORRECTION: Brought unit in. Followed recall protocal. Parts request submitted for recall

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
F100231286	32" FUEL LINE RECALL KIT	1.00	40.95	40.95

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-QUICK CONNECT	1.00	16.30	16.30

Subtotal for Job #1: 242.25

Job #2 - Warranty

COMPLAINT: BLACK TANK HEATER IS COMING LOOSE

CAUSE: Tank heater

CORRECTION: Brought unit in. Saw black tank heater was falling off of unit. Cleaned area with mineral spirits and dried off. Then applied tape prime to both areas and used a piece of wood and jack to put pressure on spot while tape prime sets in to stick back to heater. Removed jack from wood holding tank heater up. Tank heater is sticking to tank

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: USB CHARGER BY DOOR IS NOT WORKING

CAUSE: Usb charger

CORRECTION: Brought unit in tested usb chatger and had no power coming to charger. Paetd request submitted for usb charger



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,





Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
F100462835	Black Dual USB-A 2.4 AMP & 3.0 AMP U	1.00	19.96	19.96

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - JOBS 3,4,5,8	1.00	144.31	144.31

Subtotal for Job #3: 201.27

Job #4 - Warranty

COMPLAINT: HOLE IN FRONT PANEL OF BED. MUST OF BEEN NOTED ON DAF - THERE IS BLUE TAPE NEAR IT.

CAUSE: Bed panel

CORRECTION: Brought unit in. Found hole in bed panel. Parts request submitted for panel and sesm tape

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	277.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
F100320274	TAPE SEAM VINYL 1" FAWN MAPLE	10.00	0.17	1.70
F100403479	LAUAN, 1/8" X 48" X 96" VERTICAL GRA	1.00	61.87	61.87

Subtotal for Job #4: 341.07

Job #5 - Warranty

COMPLAINT: TV IS RUBBING ON CEILING WILL NOT CLOSE FLUSH AGAINST WALL.

CAUSE: Tv

CORRECTION: Brought unit in. Checked tv and it is not locking all ghe way in place. Noticed its missing a turn handle to secure it in place on tv bracket parts request submitted

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
C01219388	BLACK ADJUSTMENT KNOB FOR PIVOTING T	1.00	8.05	8.05

Subtotal for Job #5: 26.55

Job #6 - External

COMPLAINT: Transferred to BAS*78924 on 30 JAN 26
 Estimate amount was 0.00
 GENERATOR VIBRATION BUMPERS ARE
 NIOISY/SQUEAKY WHEN GENERATOR



STARTS/STOPS

CAUSE: Generator

CORRECTION: Turned on generator and saw bumpers needed lubricant. Added penetrating lube and noise softened.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #6: 0.00**Job #7 - External**

COMPLAINT: Transferred to BAS*78924 on 30 JAN 26

Estimate amount was 0.00

CHECK ROOF SEALANTS - TOUCH UP AS NEEDED

CAUSE: Roof sealant

CORRECTION: Grabbed lift went to roof of unit and checked all dicor. All dicor looked good with no cracks or voids

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #7: 0.00**Job #8 - Warranty**

COMPLAINT: LP SAFETY CHECK

CAUSE: Lp test

CORRECTION: Starting pressure was 13.5iwc. At 50% with furnace and range is 11iwc. Lock up stops at 13iwc. Fornleak test ran at 8iwc for 5mins. Had a leak during test. Checked at water heater, furnace, and range for leak. None found. Testing at range to check for leak. After checking and capping all appliances besides range. And spraying manifold and lines sprayed at regulator and found vent was leaking. Removed lp line from regulator. Removed regulator from tank and took to vise to remove adapter. Once removed placed lp thread tape on and placed adapter on new regulator. Went to unit and put thread tape on lp line. Attached lp line to regulator and then to tank. Attached all lp lines back to appliances and turned tank on and checked for leaks. Ran new lp test. Starting pressure was 11.5iwc. 50% with range and furnace is 10iwc. Adjusted to 11. Lock up pressure stops at 13.5iwc. Running leak test at 8 for 5mins. Unit passed leak test. No new leaks found

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	92.50

Parts

Part #	Description	Qty	Price	Total
06-0450	MEGR-298P REGULATOR	1.00	56.41	56.41
C01228791	REGULATOR, 2-STAGE ASME W/POL BRASS	1.00	37.45	37.45

Subtotal for Job #8: 186.36W/O: 78872
Promised Date: 28 FEB 26Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

W/O: 78872
Promised Date: 28 FEB 26

Parts Total:	226.39
Labour Total:	647.50
Sublet Total:	0.00
Extras Total:	160.61
WORK ORDER TOTAL:	1,034.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Feb 2026

Customer Work
Order



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

