

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2602093
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB3SU045647
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	103 / 103
Labor rate:	\$185.00	ITEM #	CAT261BH-8
OWNER INFORMATION		DEALER RO #	78887
CHUBBY CHOW LLC		CLAIM START DATE	03/06/2026
PO BOX 3641		CLAIM END DATE	01/01/1900
Evansville, IN 47735			
USA			
Retail Date of Purchase	04/19/2025	WARRANTY EXPIRATION DATE	04/19/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-49-01-11-000591	LED Light Strip - Front Cap - Exterior/Front, Fiberglass Cap, Cab Over/Replace/ Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-06 14:26:09 :: LED LIGHT OUT ON BOTH FRONT MOLDING STRIPS Led strips Brought unit in. Turned on front led strips. Noticed both had bulbs out on them. Pictures taken. Parts request submitted			
Model#	Dlr Sub Hrs	0.60	Sub Labor Amt	\$111.00
Serial#	Appr Hrs	0.60	Appr Labor Amt	\$111.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	20-43-24-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-09 14:17:25 :: A LOT OF BUBBLES IN THE DECALS Bubbles in decal Took pictures of decal bubbles went around unit and made small hole to remove bubbles pictures taken.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
	Notes			
	EXCESSIVE AMOUNT REQUESTED. CHANGED TO FLAT RATE			
	THE REQUESTED REPAIR CAN BE COMPLETED IN THE FLAT RATE TIME ALLOTTED			

Submitted	Labor Amt	\$166.50	Approved	Labor Amt	\$166.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$166.50		Total	\$166.50

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.