



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78918



CUSTOMER WORK ORDER

WO #: 78918

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0206 CHECK PREAUTH

Stock #: 11690
Stock Desc: 2026 TT KEYSTONE
SPRINGDALE 2300BH
Chassis #: 4YDTSGK29T7101268
Serial #: 4YDTSGK29T7101268
Mileage: 0
Licence:

Invoice #:
Date In: 29 JAN 26
Promised:
Date Sched:
Completed: 06 FEB 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: Checked appliances brakes tire pressure torqued lugs checked electrical system and plumbing system checked cabinets doors and drawers filled l.p tanks and ran l.p drop test. Installed battery box. Documented model and serial numbers. Removed packaging from appliances.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: located water pump.ran a.f. through all lines and fixtures. drained all tanks.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C
Z990	WINTERIZE UNIT	ZMS	N/C



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	3.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: STAIN ON COUCH CUSION

CAUSE: Stain on couch

CORRECTION: Removed stain with mineral spirits and a rag.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	36.00

Subtotal for Job #1: 36.00

Job #2 - Warranty

COMPLAINT: INSIDE VENT SHROUD IS CRACKED IN BATHROOM

CAUSE: replace vent shroud.

CORRECTION: removed damaged vent shroud and took measurements. traced out new shroud and cut to fit. installed new shroud on vent.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	18.00

Parts				
Part #	Description	Qty	Price	Total
398049	Vent - Garnish - 5 1/4" - White	1.00	5.16	5.16

Subtotal for Job #2: 23.16

Job #3 - Warranty

COMPLAINT: ENTRY DOOR HARD TO LATCH

CAUSE: Latch on the entry door is out to far.

CORRECTION: Moved the latch over towards the frame with a hammer.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	36.00

Subtotal for Job #3: 36.00

Parts Total: 5.16
 Labour Total: 90.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 95.16

Customer #: 1000
 BASDEN'S AMERICAN RV,



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Feb 2026

W/O: 78918

Customer Work
Order



Customer #: 1000
BASDENS AMERICAN RV,

