



Pre-Authorization

Pre-Authorization number: PREAUTH700 Reference no.78931 Status: Approved
 52 (PA03962404)

Servicing Dealer 1194
 Name Basden's American RV
 Address 600 E Baseline Rd Evansville, IN 47725
 VIN 4YDTSGE17TW101763
 Retail sold on

Root	Operation Description	Sublet	Sub Hours	Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
6100602A	City Water Entry - Repair	0	0.1	0.1		1	0.2	Complaint: SCREEN MISSING IN THE CITY WATER Cause: Missing screen washer Correction: Opened the lid for the city water connection during the pdi and found the screen washer was missing. Got new screen washer then put it in to continue the pdi. No leaks occurred.
6101202A	Fresh Water Tank Fill - Repair	0	0.2	0.2		1	0.2	Complaint: Vent hose for fresh tank fill is too long Cause: Hose to long Correction: Unscrewed the hose clamp. Pulled off the hose and cut it about 1.5 inches the push the hose back on the tank. Tightened the hose clamp. Now it can vent when filling the fresh tank.
2200902B	Roof Vents - 14"x 14" - All - Garnish	0	0.1	0.1		1	0.1	Complaint: Crank up vent in bathroom has a crack Cause: Crack in the plastic Correction: Took pictures of the crack then put in a parts request for new plastic trim for the vent.
Pre-Authorization number: PREAUTH70052			0.4					

For paper claims only use one pre-authorization number per warranty claim form.
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.