



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH704 Reference no.78970 95 (PA03962842	Status	Approved			
Servicing Dealer 1194	Name Basden's American RV	Address 600 E Baseline Rd Evansville, IN 47725	VIN 4YDTSGG19TW101938	Retail sold on		

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root	Operation Description	Sublet	Sub Hours	Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
2200908B	Roof Vents - 14" x 14" - All - Garnish	0	0.1	0.1		1	0.1	Complaint: VENT IN BATHROOM GARNISH IS CRACKED Cause: Bathroom vent trim ring cracked Correction: Took old trim ring off and installed the new one. Good to go
2300108F	Entrance Door - Hinged - Adjust Door or Lock	0	0.2	0.2		1	0.2	Complaint: ENTRY DOOR HARD TO OPEN Cause: Entry door hard to open Correction: I adjusted the latch on the door and it works properly now
3201803A	Decorative Wood Trim - Repair - per piece	0	0.1	0.1		1	0.1	Complaint: WALL PAPER PEELING NEAR THE SINK Cause: Wall tape loose Correction: Sprayed some adhesive and pushed tape back down and its good to go
6103506B	Pump - Replace	0	0.6	0.3		1	0.3	Complaint: WATER PUMP NOT WORKING Cause: Water pump doesn't work Correction: After inspection of the water pump. The fuse was blown i fixed that then it wouldn't start up i got it to start loose connection. Now it won't prime. Put a parts request in for a new one. Installed a new water pump and it works properly system good to go
4208308B	Range Top Cover	0	0.5	0		1	0.2	Complaint: 2 BURNER STOVE SCRATCHED Cause: UNIT IS SCRATCHED NEEDS TO REPLACE Correction: REPLACE STOVE TOP

KRV - Please retain part for possible return or additional photos. Keystone will notify you within 48 hours of submitting your claim for disposition of the part.
Model+serial #s / vendor tags from complete component / vendor markings required.

KRV The submitted item is considered acceptable in regard to functionality and aesthetic appearance as stated in Keystone Policy and Procedure Manual

Pre-Authorization number: PREAUTH70495

0.7

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.