

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78972
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11704 - 2026 COUGAR HALF-TON 28BHS 4YDTCGN27TV504234
VIN: 4YDTCGN27TV504234 HIN: SER#: 4YDTCGN27TV504234
Mileage: 0 Work Order Comp: 19 FEB 26
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 05 FEB 26 Inv #: 426596

WO # Job # Description JOB INFORMATION

78972 3 HANDLE ON BLACK TANK VALVE MISSING
Handle for the gate valve is missing
Painted a new grey handle black. Installed handle on gate valve.
78972 1 SCRATCH ON CABINET SIDE OF MASTER BED
There is a scratch on the panel next to the bed.
Removed scratch with mineral spirits and a rag.
78972 2 FRONT ENTRY DOOR NEEDS ADJUSTED
The latch plate is hitting the door.
Moved latch plate over with a hammer.
78972 4 GLUE ON BATHROOM MIRROR
Glue on mirror.
Removed glue with mineral spirits and a rag.
78972 5 REAR SCREEN DOOR NEEDS ADJUSTEDE
The screen door is hitting the latch plate for the entry door.
Moved the latch plate over with a hammer to clear the door.
78972 6 THE SEAL FOR THE TOILET HOLDING WATER
The toilet bowl is not holding water. Went to parts room and got
a inner seal. After trying to remove the original seal.I noticed
that the flapper was not in the correct location.
Pull the flapper into the channel that its supposed to sit in.
The toilet bowl now holds water.

Claim : 78972

```

*****
WO #      Job #   Description      JOB INFORMATION
*****

```

```

*****
Part No   Job#   Description      PARTS           Qty   Price   Total
*****
VLPT1003-6MNV   3   VALVE HANDLE - METAL           1.00   8.00   8.00

```

```

*****
Lab Code  Job#   Description      LABOUR           Hrs   Rate   Total
*****
Z990      3   MISCELLANEOUS REPAIR           0.20  180.00  36.00
Z990      1   MISCELLANEOUS REPAIR           0.20  180.00  36.00
Z990      2   MISCELLANEOUS REPAIR           0.20  180.00  36.00
Z990      4   MISCELLANEOUS REPAIR           0.20  180.00  36.00
Z990      5   MISCELLANEOUS REPAIR           0.20  180.00  36.00
Z990      6   MISCELLANEOUS REPAIR           0.30  180.00  54.00

```

```

Parts Total:      8.00
Labour Total:     234.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 242.00

Customer Signature: _____

Date: _____