

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79010
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11709 - 2026 REMOTE 12R 5ZT2RMAC8TL019637

VIN: 5ZT2RMAC8TL019637 HIN:

SER#: 5ZT2RMAC8TL019637

Mileage: 0

Work Order Comp: 28 FEB 26

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 11 FEB 26

Inv #: 427086

WO # Job # Description JOB INFORMATION

79010 3 LP QUICK CONNECT HOSE FOR GRIDDLE WONT CONNECT TO FRAME
CONNECTION
Lp hose
Took pictures of the lp hose and put in a parts request got new
hose and installed

79010 1 TANK HEATERS FALLING OFF
Heating pad
The heating pad on the fresh tank and grey tank wasnt sticking to
the tanks. Applied 3m tape primer then pressed them against the
tank and added tape for temporary hold.

79010 2 FURNACE FAN IS TICKING
Fan blade
During the pdi the turned on the furnace and the furnace fan was
ticking. Shut off the lp then unscrewed the furnace cover.
Disconnected the power wires from the furnace. Disconnected the lp
line. Unscrewed the furnace from the cabinet. Bench tested the
furnace and found the big fan blade was running the metal frame.
Disassembled the furnace. Unscrewed the fan blade from the motor.
Shaved the fan blade at the ends where it was rubbing. Screwed on
the fan to the motor and assembled the furnace. Tested the
furnace by bench testing. Furnace was quiet after, rotated the
furnace to make sure it was solid and quiet. Put the furnace
back inside the camper. Connected the lp line and wires. Mounted
the furnace to the cabinet and screwed on the cover. Tested the

Claim : 79010

 WO # Job # Description JOB INFORMATION

furnace again inside the camper and it still was quiet. Took pictures of the process.

| Part No | Job# | Description | PARTS | Qty | Price | Total |
|------------|------|---------------------------------|-------|------|-------|-------|
| F100192196 | 3 | HOSE, LP 48" WITH QUICK DISCONN | EC | 1.00 | 23.44 | 23.44 |

| Lab Code | Job# | Description | LABOUR | Hrs | Rate | Total |
|----------|------|-----------------------------|--------|------|--------|--------|
| Z990 | 3 | MISC LABOUR CODE (EXTERNAL) | EX | 0.00 | 185.00 | 0.00 |
| Z990 | 3 | MISC LABOUR CODE (EXTERNAL) | EX | 0.05 | 185.00 | 9.25 |
| Z990 | 1 | MISC LABOUR CODE (EXTERNAL) | EX | 0.20 | 185.00 | 37.00 |
| Z990 | 2 | MISC LABOUR CODE (EXTERNAL) | EX | 0.45 | 185.00 | 83.25 |
| Z990 | 2 | MISC LABOUR CODE (EXTERNAL) | EX | 0.80 | 185.00 | 148.00 |

| Excode | Job# | Description | EXTRAS | Qty | Price | Total |
|--------|------|-------------|--------|------|-------|-------|
| FRT | 3 | UPS-HOSE | EX | 1.00 | 16.32 | 16.32 |

Parts Total: 23.44
 Labour Total: 277.50
 Sublet Total: 0.00
 Extras Total: 16.32

>>>> Claim Total: 317.26

Customer Signature: _____

Date: _____