



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79015
Promised Date:
28 FEB 26



CUSTOMER WORK ORDER

WO #: 79015

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0213 BH TO CLOSE

Stock #: 11710
Stock Desc: 2026 5W KEYSTONE
COUGAR 350LLK
Chassis #: 4YDFCGT21T2504876
Serial #: 4YDFCGT21T2504876
Mileage: 0
Licence:

Invoice #:
Date In: 11 FEB 26
Promised: 28 FEB 26
Date Sched:
Completed: 16 FEB 26
Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: Pdi

CORRECTION: Pulled unit into shop and hooked up to shore power. Checked all appliances checked water and electrical systems checked roof and antenna function. Filled l.p tanks and ran l.p drop test. Checked doors drawers and cabinets. Checked tire pressure and torqued lug nuts. Documented model and serial numbers.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: located pump. ran a.f. through all lines and fixtures. drained all tanks.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 79015
Promised Date: 28 FEB 26



Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR IS HARD TO CLOSE

CAUSE: The door is hitting the frame at the bottom corner

CORRECTION: Placed a block on the inside corner and pushed the door shut. The corner is now pushed away from the frame and shuts easily.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	36.00

Subtotal for Job #1: 36.00

Job #2 - Warranty

COMPLAINT: DOORS UNDER KITCHEN SINK

CAUSE: The doors are hitting each other.

CORRECTION: Moved doors over with a hammer.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	18.00

Subtotal for Job #2: 18.00

Parts Total: 0.00
Labour Total: 54.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 54.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Feb 2026

