



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79020
Promised Date:
28 FEB 26

CUSTOMER WORK ORDER

WO #: 79020

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 0325 CHECK TO SEE IF
CRAIG HAS INVOICE YET

Stock #: 11711
Stock Desc: 2026 TT COACHMEN
CATALINA SUMMIT 154RDX
Chassis #: 5ZT2CADC2TK014239
Serial #: 5ZT2CADC2TK014239
Mileage: 0
Licence:

Invoice #:
Date In: 12 FEB 26
Promised: 28 FEB 26
Date Sched:
Completed: 25 MAR 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*79184 on 05 MAR 26
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER CATALINA
TK014239

CAUSE: New pdi

CORRECTION: Lug nuts torqued to spec air pressure correct in 2 tires. Running lights and brake lights work properly brakes and Emergency Brakes work properly installed a new battery box. Exterior inspection entry door needs adjusted. That i got adjusted. both front cap lights are hanging downout of the track to far. One spot on off door side needs sealed. That i filled with silicone. Hitch scratched and rusty. roof inspection good but i seen were the cap lights have slid down about 2 inches and they just filled the track with silicone. Awning fabric and hardware looks and works properly Awning lights work properly. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly. All outlets work properly and USB port works properly. Tv is missing power cord. And i have to make a antenna cable. Dinette table has a broken corner. Put water in fresh tank and ran the water pump and flushed out all the lines water pump works properly. Did my lp drop tes on the stove with furnace and water heater running made no adjustments to regulator system works properly. Fixed the trim pannel under the stove. Put company stickers on it. I painted the hitch. This unit was missing the bolt hole and the propane warning stickers so i put them on there. I also put a parts request in for a new trim piece that runs along of the cabinet that got damaged in transport probably from the table that was laying on the floor when i checked this unit in.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*79184 on 05 MAR 26
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE



Customer #: 1000
BASDENS AMERICAN RV,



UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA
 DE-WINTERIZATION IS NOT INCLUDED
 NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned water pump to winterize and pumped solution through the lines to bathroom shower hot and cold then repeated for toilet kitchen faucet. Drained water heater and depressed city water inlet. Drained black tank and gray tank and fresh tank. Poured solution down drains. Used 2 gallons of winterize solution

Labor				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		JTW	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: DINETTE TABLE HAS A LARGE CHIP OUT OF IT

CAUSE: Dinette table broken and trim piece on bottom of cabinets

CORRECTION: Noticed during check in the table was damaged and laying on the floor and it must have hit the trim piece on the bottom of the cabinet i put both in for parts request

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		CCV	222.00
Parts				
Part #	Description	Qty	Price	Total
F100746815	TABLE, DINETTE 21.5" X 38" PEBBLE FA	1.00	74.13	74.13
Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-JOBS 1,3	1.00	43.38	43.38
Subtotal for Job #1:				339.51

Job #2 - Warranty

POWER CORD AND REMOTE FOR SANSUI TV
 MISSING.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		CCV	0.00
Parts				
Part #	Description	Qty	Price	Total
12774	REMOTE-RCA00002 - FOR SANSUI	1.00	51.48	51.48
12775	120Q119905-POWER CORD FOR SANSUI TV	1.00	21.45	21.45
Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-REMOTE AND CORD	1.00	14.54	14.54
Subtotal for Job #2:				87.47



W/O: 79020
 Promised Date: 28 FEB 26



Customer #: 1000
 BASDEN'S AMERICAN RV,





Job #3 - Warranty

COMPLAINT: FABRIC BUTTONS MISSING FROM TRIM PANEL OVER THE DOOR.

CAUSE: BUTTONS MISSING

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		CCV	0.00
Parts				
Part #	Description	Qty	Price	Total
F100478742	BUTTON, VINYL SNAP-ON DENIEL PEBBLE	3.00	0.13	0.39
Subtotal for Job #3:				0.39

Job #4 - Warranty

COMPLAINT: ENTRY DOOR HARD TO OPEN

CAUSE: Entry door hard to open

CORRECTION: Adjusted the hinges on the door and lubed the latch. Door works properly now

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	37.00
Subtotal for Job #4:				37.00

Job #5 - Warranty

COMPLAINT: CEILING LIGHT FELL OFF NEED TO REINSTALL

CAUSE: Light cover off

CORRECTION: During check in i found cover on the floor. So i put it on and tested the light and it work properly

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	9.25
Subtotal for Job #5:				9.25

Job #6 - Warranty

REPLACE THE TV WILL NOT PAIR

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	55.50
Parts				
Part #	Description	Qty	Price	Total
F100779215	TV,SANSUI 24" ANDROID SMART TV	1.00	163.02	163.02
Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-TV	1.00	15.05	15.05
Subtotal for Job #6:				233.57



Parts Total: 310.47
Labour Total: 323.75
Sublet Total: 0.00
Extras Total: 72.97
WORK ORDER TOTAL: 707.19

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Mar 2026

Customer Work
Order

W/O: 79020
Promised Date: 28 FEB 26



Customer #: 1000
BASDEN'S AMERICAN RV,

