

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79029
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 56502 - BARBARA GILL
Address: 4527 N CR 200 E SULLIVAN, IN

47882

Phone: 319-330-2746

Stock Number: 11541 - 2025 FREEDOM EXPRESS 247SE 5ZT2FEPB2SW030689

VIN: 5ZT2FEPB2SW030689 HIN: SER#: 5ZT2FEPB2SW030689

Mileage: 0 Work Order Comp: 11 MAR 26

Auth. No: Dealer #:

Warr. Date: 28 FEB 26 Work Order Date: 13 FEB 26 Inv #: 427288

WO # Job # Description JOB INFORMATION

- 79029 3 KITCHEN PANELING ON CABINET NOT ATTACHED
Walboard on side of kitchen cabinet is detached near the wall
I tried to find a stapler that would fit in between the slide
room wall and the cabinet. I could not find a stapler small
enough. To prevent pulling the slide room apart, I opted for
using silicone to hold the panel in place. I added silicone on
the backside between the panel block and the paneling. I then
sealed up the corner from the outside with clear silicone. I
placed foam blocks between the slide room and the cabinet to hold
overnight while the silicone cures. I checked the paneling in the
morning and it is holding in place.
- 79029 2 MICROWAVE DOOR WON'T OPEN
Microwave will not open.
I found that after using the button over 30 times, the release
started working.
- 79029 4 THE PRIVACY BLIND IN THE SLIDE ROOM FELL OFF OF THE WALL.
The screw holding the blind at the rear of the slide room window
fell out of the paneling.
I removed the valence over the blind mounting area. I found that
this blind had 3 mounting holes and only 2 had been used. The far
left screw had come out of the wall. I installed a center screw
and I replaced the 2 screws holding the blind up. I used a little
bit larger screw to keep from making new holes. The new screws
are holding tight. I reinstalled the valence.

Claim : 79029

```

*****
WO #      Job #   Description      JOB INFORMATION
*****

```

```

*****
Part No   Job#   Description      PARTS          Qty   Price   Total
*****
SIK432053    3   CLEAR SIKASIL PLUS          1.00   11.08   11.08

```

```

*****
Lab Code  Job#   Description      LABOUR          Hrs   Rate   Total
*****
Z990      3   MISC LABOUR CODE (EXTERNAL)    0.00   185.00   0.00
Z990      3   MISC LABOUR CODE (EXTERNAL)    0.30   185.00   55.50
Z990      2   MISC LABOUR CODE (EXTERNAL)    0.10   185.00   18.50
Z990      4   MISC LABOUR CODE (EXTERNAL)    0.40   185.00   74.00

```

```

Parts Total:      11.08
Labour Total:     148.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 159.08

Customer Signature: _____

Date: _____