



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79036
Promised Date:
28 FEB 26



Customer #: 56510
STOCKS, JAKE



CUSTOMER WORK ORDER

WO #: 79036

Customer: 56510 - STOCKS, JAKE -
812-589-2126

Tag:

Author: BH

Location: 0224 CHECK PREAUTH

Stock #: 11610

Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 1800BH

Chassis #: 4YDTSGG10SW104242

Serial #: 4YDTSGG10SW104242

Mileage: 0

Licence:

Invoice #:

Date In: 16 FEB 26

Promised: 28 FEB 26

Date Sched:

Completed: 24 FEB 26

Warr. Date: 19 FEB 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final

CORRECTION: Lug nuts torqued to spec running lights are working except off door side front. And door side rear tail light missing cover. I replaced the taillight cover. Brakes and Emergency Brakes work properly installed a new battery. Exterior inspection looks good. Roof inspection looks good. Awning fabric and hardware looks and works properly hooked to city water and flushed out all the lines no leaks. Stove and microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly. Did my lp drop test on the stove with furnace and water heater running made no adjustments to regulator system works properly. Put water in fresh tank and ran the water pump and it worked properly drained all the tanks

Labor

Code	Description	Mechanic	Total
PDIINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDIINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
8935	Light - Tail - Black Base - LED	1.00	N/C	N/C
285324	3/4" JACK HANDLE	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize mode and pumped 2 gallons of winterize solution through the water pump to bathroom shower cold and hot until solution was there then repeated for bathroom faucet toilet and kitchen faucet and depressed city water inlet. Drained black tank and gray tank and fresh tank.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C





Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: MARKER LIGHT NOT WORKING

CAUSE: Front running light doesn't work

CORRECTION: Took light off made sure there was a good connection it was. Tested the light after i cut the wires and it doesn't work. So i put a parts request in for a new one that we didn't have. So i went and took one off a lot unit and took a picture of the donor unit vin and marked it with blue tape to replace it when it comes in. And wired the light up on sold unit and it works properly. And then i sealed it with clear silicone. Good to go

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		JTW	36.00
Parts				
Part #	Description	Qty	Price	Total
748366	Light - Clearance - Marker - Oval -	1.00	2.11	2.11
Subtotal for Job #1:				38.11

Parts Total: 2.11
 Labour Total: 36.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 38.11

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 24 Feb 2026

Customer Signature : _____

