



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79048



CUSTOMER WORK ORDER

WO #: 79048 (Appointment Date: 17 FEB 2026 - Time: 08:00pm)

Customer: 55846 - HARRIS, QYENTIN -

Tag:

Author: GA

Location: 0220 CHECK STATUS WITH
SR

Stock #:

Stock Desc: 2022 FOREST RIVER

WILDWOOD XLITE

Chassis #:

Serial #: 4X4TWDD23N7373041

Mileage:

Licence:

Invoice #: 426575

Date In: 18 FEB 26

Promised:

Date Sched:

Completed: 18 FEB 26

Warr. Date:

Job #SUMMER - External

COMPLAINT: DE-WINTERIZE UNIT

CAUSE: Dewinterizing

CORRECTION: Filled the fresh tank 1/3 full then opened each faucet to flush out antifreeze, no antifreeze found. Drained the black and grey tanks.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #SUMMER: 0.00

Job #ROOFT - External

COMPLAINT: INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF SEALANT INCLUDED.

CAUSE: Cracks and voids

CORRECTION: Got on the roof and inspected the roof membrane and sealer. Found cracks and voids in the sealer. Cleaned and applied dicor sealer as necessary.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #LPTEST - External

COMPLAINT: PERFORM LP SYSTEM LEAK CHECK

CAUSE: Lp safety check

Customer #: 55846
HARRIS, QYENTIN



CORRECTION: Connected the manometer to the lp quick connection then turned on the lp tank. Turned on the furnace and water heater then adjusted the lp regulator. Filled out the lp sheet. Disconnected the manometer from the lp quick connection. Shut off the lp tank. No leaks occurred.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #LPTEST: 0.00

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CAUSE: Quick connection

CORRECTION: Took pictures of the lp quick connection. Does not have faulty connection.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	18.50

Subtotal for Job #22V243: 18.50

Parts Total: 0.00
Labour Total: 18.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 18.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Feb 2026

Customer #: 55846
HARRIS, QYENTIN